

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

|                 |                                        |      |       |                   |       |
|-----------------|----------------------------------------|------|-------|-------------------|-------|
| INSPECTION DATE | 2026/7/14                              | MAKE | CAT   | MODEL             | 336FL |
| SERIAL          | CAT0336FPDSW10008                      |      | STAMP | CAT0336FPDSW10008 |       |
| HR METER        | 7223 / 7233                            | HR   | YEAR  | YR                |       |
| CAB/CNP         | ROPS CAB / CAB / ROPS CNP / CNP / NONE |      | SHOE  | 700G              |       |

|                           |       |      |                                 |          |
|---------------------------|-------|------|---------------------------------|----------|
| ENGINE : MODEL            |       | C9.3 | S/N                             | SYE15771 |
| Oil leakage               | FAIR  | Attn |                                 |          |
| Blow-By                   | FAIR  | Attn | A LITTLE · MIDDLE · SEVERE      |          |
| Sound                     | FAIR  | Attn |                                 |          |
| Oil                       | FAIR  | Attn |                                 |          |
| Exhaust Color             | FAIR  | Attn |                                 |          |
| US EPA                    | YES   | NO   |                                 |          |
| MAIN PUMP                 |       |      |                                 |          |
| Sound                     | FAIR  | Attn |                                 |          |
| Oil leakage               | FAIR  | Attn |                                 |          |
| Power                     | FAIR  | Attn |                                 |          |
| COOLING SYSTEM            |       |      |                                 |          |
| Radiator                  | FAIR  | Attn |                                 |          |
| Oil Cooler                | FAIR  | Attn |                                 |          |
| OPERATING SYSTEM          |       |      |                                 |          |
| Swing                     | FAIR  | Attn |                                 |          |
| Travel                    | FAIR  | Attn |                                 |          |
| INTERIOR See Photos. 写真参照 |       |      |                                 |          |
| INTERIOR COND.            | CLEAN | FAIR | DIRTY                           |          |
| Operator's Seat           | FAIR  | Attn |                                 |          |
| Glasses                   | FAIR  | Attn | F割れあり UPPER WINDSHIELD: CRACKED |          |
| AirCon                    | A/C   | H/C  | H only                          | C only   |
| None                      |       |      |                                 |          |
| BOOM / ARM / BKT          |       |      |                                 |          |
| Boom                      | FAIR  | Attn |                                 |          |
| Boom Cylinder             | FAIR  | Attn |                                 |          |
| Arm                       | FAIR  | Attn |                                 |          |
| Arm Cylinder              | FAIR  | Attn |                                 |          |
| ATTACHMENT                | FAIR  | Attn | ガタあり LOOSE                      |          |
| BKT Cylinder              | FAIR  | Attn | 傷あり SCRATCHED                   |          |

|                                                                                                                                                     |                                             |  |  |  |   |
|-----------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------|--|--|--|---|
| UNDERCARRIAGE : See Photos. 写真参照                                                                                                                    |                                             |  |  |  |   |
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)                                                                                        |                                             |  |  |  | 3 |
| COMMENT<br>左Fキャリアローラー曲がりあり FRONT LEFT CARRIER ROLLER: BENT                                                                                          |                                             |  |  |  |   |
| BKT                                                                                                                                                 | (STD / SLOPE / NARROW / SKELETON / OTHER( ) |  |  |  |   |
| Lever                                                                                                                                               | LONG • (WRIST)                              |  |  |  |   |
| Multi                                                                                                                                               | (MULTI) • 2 • NO                            |  |  |  |   |
| ARM-CRANE                                                                                                                                           | YES • (NO)                                  |  |  |  |   |
| BLADE                                                                                                                                               | YES • (NO)                                  |  |  |  |   |
| OFFSET                                                                                                                                              | YES • (NO)                                  |  |  |  |   |
| OFFSET Cylinder                                                                                                                                     | FAIR • Attn                                 |  |  |  |   |
| Piping                                                                                                                                              | (YES) • NO Breaker only • Multi             |  |  |  |   |
| COMMENT<br>ブーム背面ホース破れあり SOME HOSE AROUND BOOM: A LITTLE DAMAGED<br>旋回モーター周り油污れあり AROUND SWING MOTOR: OIL STAINS<br>燃料メーター不良 FUEL GAUGE: MALFUNCTION |                                             |  |  |  |   |
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)                                                                                |                                             |  |  |  | 3 |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。