

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/7/15	MAKE	HITACHI	MODEL	ZH210K-5B
SERIAL	HCMDCSA2A00020148		STAMP	HCMDCSA2A00020148	
HR METER	11591	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

ENGINE : MODEL		4HK1	S/N	723787
Oil leakage	FAIR	Attn		
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR	Attn		
Oil	FAIR	Attn		
Exhaust Color	FAIR	Attn		
US EPA	YES	NO		
MAIN PUMP				
Sound	FAIR	Attn		
Oil leakage	FAIR	Attn	にじみあり OIL OOZING	
Power	FAIR	Attn		
COOLING SYSTEM				
Radiator	FAIR	Attn		
Oil Cooler	FAIR	Attn		
OPERATING SYSTEM				
Swing	FAIR	Attn	ガタあり SWING: LOOSE	
Travel	FAIR	Attn		
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN	FAIR	DIRTY	
Operator's Seat	FAIR	Attn		
Glasses	FAIR	Attn		
AirCon	A/C	H/C	H only	C only
None				
BOOM / ARM / BKT				
Boom	FAIR	Attn		
Boom Cylinder	FAIR	Attn	左右油漏れあり CYLINDERS: OIL LEAKING	
Arm	FAIR	Attn	ガタあり LOOSE	
Arm Cylinder	FAIR	Attn	油漏れ小 OIL LEAKING	
ATTACHMENT	FAIR	Attn		
BKT Cylinder	FAIR	Attn	傷あり SCRATCHED	

UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3		
COMMENT			
スイベル下油汚れあり BOTTOM OF SWIVEL: OIL STAINS			
BKT	(STD / SLOPE / NARROW / SKELETON / OTHER())		
Lever	LONG ▪ (WRIST)		
Multi	MULTI ▪ 2 ▪ (NO)		
ARM-CRANE	(YES) ▪ NO		
BLADE	YES ▪ (NO)		
OFFSET	YES ▪ (NO)		
OFFSET Cylinder	FAIR ▪ Attn		
Piping	(YES) ▪ NO	Breaker only ▪ (Multi)	
COMMENT			
オイルフィルターにじみあり OIL FILTER: OIL OOZING			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。