

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/7/14	MAKE	HITACHI	MODEL	ZX135USK-5B
SERIAL	HCMDAEA1E00093555		STAMP	HCMDAEA1E00093555	
HR METER	9396	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G	

ENGINE : MODEL		4JJ1	S/N	174663
Oil leakage	FAIR · Attn			
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE		
Sound	FAIR · Attn			
Oil	FAIR · Attn			
Exhaust Color	FAIR · Attn			
US EPA	YES · NO			
MAIN PUMP				
Sound	FAIR · Attn			
Oil leakage	FAIR · Attn	配管にじみあり SOME PIPE: OIL OOZING		
Power	FAIR · Attn			
COOLING SYSTEM				
Radiator	FAIR · Attn			
Oil Cooler	FAIR · Attn			
OPERATING SYSTEM				
Swing	FAIR · Attn	ガタあり SWING: LOOSE		
Travel	FAIR · Attn			
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN · FAIR · DIRTY			
Operator's Seat	FAIR · Attn			
Glasses	FAIR · Attn	右側コーキングあり RIGHT SIDE GLASS: CAULKING		
AirCon	A/C · H/C · H only · C only · None			
BOOM / ARM / BKT				
Boom	FAIR · Attn			
Boom Cylinder	FAIR · Attn			
Arm	FAIR · Attn	ガタあり LOOSE		
Arm Cylinder	FAIR · Attn	油漏れあり OIL LEAKING		
ATTACHMENT	FAIR · Attn			
BKT Cylinder	FAIR · Attn			

UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3
COMMENT					
左キャリアローラー曲がりあり LEFT CARRIER ROLLER: BENT					
BKT	(STD / SLOPE / NARROW / SKELETON / OTHER()				
Lever	LONG ▪ (WRIST)				
Multi	MULTI ▪ 2 ▪ (NO)				
ARM-CRANE	(YES) ▪ NO	*1			
BLADE	YES ▪ (NO)				
OFFSET	YES ▪ (NO)				
OFFSET Cylinder	FAIR ▪ Attn				
Piping	(YES) ▪ NO	Breaker only ▪ Multi			
COMMENT					
フード上手すりあり HANDRAIL: PUTTING ON REAR PART OF TOP OF BODY					
コントロールバルブ油漏れあり CONTROL VALVE: OIL LEAKING					
*1 半径表示変わらない					
*1 OPERATING RADIUS: NOT CHANGING TO DISPLAY					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。