

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/7/17	MAKE	SUMITOMO	MODEL	SH120-3
SERIAL	SMT120A3H00SC7571			STAMP	SMT120A3H00SC7571
HR METER	17080	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	700G

ENGINE : MODEL		S/N
Oil leakage	FAIR • <u>Attn</u> *	*1
Blow-By	FAIR • Attn	A LITTLE • MIDDLE • SEVERE
Sound	FAIR • Attn	
Oil	FAIR • Attn	
Exhaust Color	FAIR • Attn	
US EPA	YES • <u>NO</u>	
MAIN PUMP		
Sound	FAIR • Attn	
Oil leakage	FAIR • <u>Attn</u>	油漏れあり OIL LEAKING
Power	FAIR • Attn	
COOLING SYSTEM		
Radiator	FAIR • Attn	
Oil Cooler	FAIR • Attn	
OPERATING SYSTEM		
Swing	FAIR • Attn	
Travel	FAIR • Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN • <u>FAIR</u> • DIRTY	
Operator's Seat	FAIR • <u>Attn</u>	フレーム露出あり FRAME: PARTLY BARED
Glasses	FAIR • Attn	
AirCon	<u>A/C</u> • H/C • H only • C only • None	
BOOM / ARM / BKT		
Boom	FAIR • Attn	
Boom Cylinder	FAIR • <u>Attn</u> *	*2
Arm	FAIR • Attn	
Arm Cylinder	FAIR • <u>Attn</u>	にじみあり OIL OOZING
ATTACHMENT	FAIR • Attn	
BKT Cylinder	FAIR • Attn	ガタあり LOOSE

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
COMMENT	
BKT	STD / <u>SLOPE</u> / NARROW / SKELETON / OTHER ()
Lever	LONG • <u>WRIST</u>
Multi	MULTI • 2 • <u>NO</u>
ARM-CRANE	YES • NO *3
BLADE	YES • <u>NO</u>
OFFSET	YES • <u>NO</u>
OFFSET Cylinder	FAIR • Attn
Piping	YES • NO Breaker only • <u>Multi</u>
COMMENT	
ブーム背面ホースひび割れあり SOME HOSE AROUND BOOM: CRACKED	
*1 ブロック周りにじみあり AROUND ENGINE BLOCK: OIL OOZING	
*2 右側油漏れ小、左側にじみあり	
*2 RIGHT CYLINDER: OIL LEAKING, LEFT CYLINDER: OIL OOZING	
*3 E-03エラー表示、ブザー音あり	
*3 "E-03" ERROR DISPLAY, WARNING SOUNDS: ON	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。