

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/7/15	MAKE	SUMITOMO	MODEL	SH120-3
SERIAL	NO PLATE			STAMP	120A3-1830
HR METER	13167	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	600G

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	
MAIN PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	油漏れ小 OIL LEAKING
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	*1
Oil Cooler	FAIR · Attn	
OPERATING SYSTEM		
Swing	FAIR · Attn	
Travel	FAIR · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · DIRTY	
Operator's Seat	FAIR · Attn	
Glasses	FAIR · Attn	*2
AirCon	A/C · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	FAIR · Attn	
Boom Cylinder	FAIR · Attn	*3
Arm	FAIR · Attn	
Arm Cylinder	FAIR · Attn	にじみあり OIL OOZING
ATTACHMENT	FAIR · Attn	ガタあり LOOSE
BKT Cylinder	FAIR · Attn	傷あり SCRATCHED

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
COMMENT	
シューイボ付 (高さ低く摩耗ありのため修理不要?)	
SPIKES ON SHOE PLATES (MUCH WORN, NOT NECESSARY TO CUT?)	
右走行モーターにじみあり RIGHT TRAVEL MOTOR: OIL OOZING	
BKT	STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · WRIST
Multi	MULTI · 2 · NO
ARM-CRANE	YES · NO
BLADE	YES · NO
OFFSET	YES · NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · NO Breaker only · Multi 5
COMMENT	
右サイドカバー変形あり RIGHT SIDE OF BODY: DEFORMED	
ドアラッチ不良 (閉めたら開かない)	
DOOR LATCH: MALFUNCTION (UNABLE TO OPEN IF SHUT THE DOOR)	
ローアイドルでリリースかけるとエンストする	
ENGINE STALLING WITH ENGINE LOAD INCREASING IN LOW IDLING	
A/C冷えない A/C: MALFUNCTION	
*1 クーラント: オイル混入あり OIL: MIXED INTO COOLANT	
*2 F下欠、ドアガラスコーキングあり	
*2 LOWER WINDSHIELD: MISSING, UPPER DOOR GLASS: CAULKING	
*3 左右油漏れ、左側シール外れあり	
*3 CYLINDERS: OIL LEAKING, LEFT CYLINDER SEAL: COME OFF	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。