

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/8/7	MAKE	TADANO	MODEL	TR-160M-3
SERIAL No.	PLATE : 525473			STAMP : TR162-0097	
HR METER	9523	HR	Odometer	85746	km
TIRE SIZE	325/95R24			YEAR	YR

ENGINE : MODEL		S/N
Oil leakage	FAIR ☒ Attn	上部油漏れあり UPPER PART OF ENGINE: OIL LEAKING
Blow-By	FAIR ☒ Attn	A LITTLE ☒ MIDDLE ☒ SEVERE
Sound	FAIR ☒ Attn	
Oil	FAIR ☒ Attn	
Exhaust Color	FAIR ☒ Attn	白煙あり WHITE FUMES

OPERATION PUMP		
Sound	FAIR ☒ Attn	
Oil leakage	FAIR ☒ Attn	
Power	FAIR ☒ Attn	

COOLING SYSTEM		
Radiator	FAIR ☒ Attn	
Oil Cooler	FAIR ☒ Attn	

OPERATING SYSTEM		
Computer	OK ☒ NG	画面映り悪い、未確認 MONITOR: BLURRED, NOT CHECKED
Swing	FAIR ☒ Attn	未確認 NOT CHECKED
Travel	FAIR ☒ Attn	未確認 NOT CHECKED

TRANSMISSION		
Transmission	FAIR ☒ Attn	
No. OF GEARS	4 GEARS	
4WD	☒ 4WD ☐ 6WD	

INTERIOR		See Photos. 写真参照
INTERIOR COND.	CLEAN ☒ FAIR ☒ DIRTY	
Operator's Seat	FAIR ☒ Attn	破れあり HUGE CUTS
Glasses	FAIR ☒ Attn	
AirCon	☒ A/C ☐ H/C ☐ H only ☐ C only ☐ None	

COMMENT	
メーターパネル不良 INDICATOR: MALFUNCTION	
ロータリー油漏れあり ROTARY: OIL LEAKING	
油漏れ箇所多数あり MANY SPOTS: OIL LEAKING	

BOOM		
No. of Section	6 SECTIONS	
CRACK/ENFORCEMENT	FAIR ☒ Attn	未確認 NOT CHECKED
DERRICKING CYL.	FAIR ☒ Attn	未確認 NOT CHECKED
EXTENSION CYL.	FAIR ☒ Attn	未確認 NOT CHECKED
JIB	YES ☒ NO	
JIB TYPE	STD ☐ PWR	
MAIN & SUB WIRE	YES ☒ NO	
FREE FALL	YES ☒ NO	
HOOK	-	

UNDERCARRIAGE :			See Photos. 写真参照
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3
TIRE WEAR	FAIR ☒ WORN ☒ UNEVEN WEAR		

COMMENT	
ヘコミ多数あり BODY: DENT	
第3ドラム付、メインS/Wあり W/3rd DRUM, W/MAIN SWITCH	

OUTRIGGERS					
OUTRIGGERS	☒ X ☐ H				
OUTRIGGERS COND.	FAIR ☒ Attn	*1			
Oil leakage (JACK CYL.)	FRONT	L ☒ R	REAR	L ☐ R	
Oil leakage (SLIDE CYL.)	FRONT	L ☐ R	REAR	L ☐ R	

COMMENT	
アボロン仕様のためクレーン操作できない	
AVOLON PILING RIG (UNABLE TO OPERATE CRANE PART)	
*1 アウトリガー下で操作	
*1 NEED TO OPERATE THE OUTRIGGERS FROM OUTSIDE @SAKURA YARD	
HOOK: 16t, BALL, SINGLE TOP, HOOK HOLDER, WEDGE SOCKET, AUGER (1 AXIS)	
AVOLON LEADER: 4.5m × 2, 3m × 1, 2m × 1, 1.5m END	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。