

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

|                 |                                        |      |        |        |         |
|-----------------|----------------------------------------|------|--------|--------|---------|
| INSPECTION DATE | 2026/9/10                              | MAKE | YANMAR | MODEL  | VIO27-2 |
| SERIAL          | 20733B                                 |      | STAMP  | 20733B |         |
| HR METER        | 6474                                   | HR   | YEAR   | YR     |         |
| CAB/CNP         | ROPS CAB / CAB / ROPS CNP / CNP / NONE |      | SHOE   | 300R   |         |

| ENGINE : MODEL            |                                    | S/N                            | 46531 |
|---------------------------|------------------------------------|--------------------------------|-------|
| Oil leakage               | FAIR · Attn                        |                                |       |
| Blow-By                   | FAIR · Attn                        | A LITTLE · MIDDLE · SEVERE     |       |
| Sound                     | FAIR · Attn                        |                                |       |
| Oil                       | FAIR · Attn                        |                                |       |
| Exhaust Color             | FAIR · Attn                        |                                |       |
| US EPA                    | YES · NO                           |                                |       |
| MAIN PUMP                 |                                    |                                |       |
| Sound                     | FAIR · Attn                        |                                |       |
| Oil leakage               | FAIR · Attn                        |                                |       |
| Power                     | FAIR · Attn                        |                                |       |
| COOLING SYSTEM            |                                    |                                |       |
| Radiator                  | FAIR · Attn                        |                                |       |
| Oil Cooler                | FAIR · Attn                        |                                |       |
| OPERATING SYSTEM          |                                    |                                |       |
| Swing                     | FAIR · Attn                        |                                |       |
| Travel                    | FAIR · Attn                        | 右走行が弱い RIGHT TRACK: WEAK POWER |       |
| INTERIOR See Photos. 写真参照 |                                    |                                |       |
| INTERIOR COND.            | CLEAN · FAIR · DIRTY               |                                |       |
| Operator's Seat           | FAIR · Attn                        | 切れあり CUTS                      |       |
| Glasses                   | FAIR · Attn                        |                                |       |
| AirCon                    | A/C · H/C · H only · C only · None |                                |       |
| BOOM / ARM / BKT          |                                    |                                |       |
| Boom                      | FAIR · Attn                        |                                |       |
| Boom Cylinder             | FAIR · Attn                        |                                |       |
| Arm                       | FAIR · Attn                        |                                |       |
| Arm Cylinder              | FAIR · Attn                        |                                |       |
| ATTACHMENT                | FAIR · Attn                        |                                |       |
| BKT Cylinder              | FAIR · Attn                        |                                |       |

|                                                                             |                                             |                      |
|-----------------------------------------------------------------------------|---------------------------------------------|----------------------|
| <b>UNDERCARRIAGE :</b>                                                      |                                             | <b>See Photos.</b>   |
| <b>RUST</b> (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)         |                                             | <b>2</b>             |
| <b>COMMENT</b>                                                              |                                             |                      |
|                                                                             |                                             |                      |
| BKT                                                                         | (STD / SLOPE / NARROW / SKELETON / OTHER( ) |                      |
| Lever                                                                       | LONG ▪ (WRIST)                              |                      |
| Multi                                                                       | MULTI ▪ 2 ▪ (NO)                            |                      |
| ARM-CRANE                                                                   | YES ▪ (NO)                                  |                      |
| BLADE                                                                       | (YES) ▪ NO                                  |                      |
| OFFSET                                                                      | YES ▪ (NO)                                  |                      |
| OFFSET Cylinder                                                             | FAIR ▪ Attn                                 |                      |
| Piping                                                                      | YES ▪ (NO)                                  | Breaker only ▪ Multi |
| <b>COMMENT</b>                                                              |                                             |                      |
|                                                                             |                                             |                      |
| <b>RUST of BODY</b> (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) |                                             | <b>2</b>             |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。