

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/7/9	MAKE	KOMATSU	MODEL	PC228US-8
SERIAL	52031		STAMP	KMTPC226A02052031	
HR METER	7757	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

ENGINE : MODEL		6D107E-1	S/N	26619359
Oil leakage	FAIR	Attn		
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR	Attn		
Oil	FAIR	Attn		
Exhaust Color	FAIR	Attn		
US EPA	YES	NO		
MAIN PUMP				
Sound	FAIR	Attn		
Oil leakage	FAIR	Attn		
Power	FAIR	Attn		
COOLING SYSTEM				
Radiator	FAIR	Attn		
Oil Cooler	FAIR	Attn		
OPERATING SYSTEM				
Swing	FAIR	Attn		
Travel	FAIR	Attn		
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN	FAIR	DIRTY	
Operator's Seat	FAIR	Attn	破れあり CUT	
Glasses	FAIR	Attn		
AirCon	A/C	H/C	H only	C only
				None
BOOM / ARM / BKT				
Boom	FAIR	Attn		
Boom Cylinder	FAIR	Attn		
Arm	FAIR	Attn		
Arm Cylinder	FAIR	Attn		
ATTACHMENT	FAIR	Attn	ガタあり LOOSE	
BKT Cylinder	FAIR	Attn		

UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					2
COMMENT					
両側スプロケット摩耗、一部欠けあり SPROCKETS: WORN, PARTLY CHIPPED OFF					
左側ピンブッシュクラックあり SOME LEFT PIN BUSHES: CRACKED					
右側トラックローラー不良あり SOME RIGHT TRACK ROLLER: MALFUNCTION					
BKT	(STD / SLOPE / NARROW / SKELETON / OTHER()				
Lever	LONG • WRIST				
Multi	MULTI • NO				
ARM-CRANE	(YES) • NO	*1			
BLADE	YES • NO				
OFFSET	YES • NO				
OFFSET Cylinder	FAIR • Attn				
Piping	YES • NO	Breaker only • Multi			
COMMENT					
ボディ両側下部リペイントあり REVOLVING FRAME: REPAINTED					
A/C冷えない A/C: MALFUNCTION					
ファンベルト異音あり FAN BELT: NOISES					
Iリンク、Hリンクガタ大 I-LINKS & H-LINK: MUCH LOOSE					
*1 クレーンモード入るがエラー警告表示あり					
*1 "E50" ERRORS DISPLAY (CRANE MODE: ABLE TO TURN ON)					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。