

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2026/7/23	MAKE	KOMATSU	MODEL	D60P-6	
SERIAL	34801			STAMP	D60P6-34801	
HR METER	3474	HR	SHOE	950LGP	YEAR	YR
BLADE	STRAIGHT / ST/TILT PAT / ANGLE / OTHER			CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	

ENGINE : MODEL		S/N	
Oil leakage	FAIR · (Attn)	ヘッドカバーにじみあり HEAD COVER: OIL OOZING	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR · Attn		
Oil	FAIR · Attn		
Exhaust Color	FAIR · Attn		
US EPA	YES · (NO)		
OPERATION PUMP			
Sound	FAIR · Attn		
Oil leakage	FAIR · Attn		
Power	FAIR · Attn		
COOLING SYSTEM			
Radiator	FAIR · Attn		
Oil Cooler	FAIR · Attn		
TRANSMISSION & TRAVEL			
T/M TYPE	PS · (DD)	DIFF. STEERING	YES · (NO)
Transmission	FAIR · Attn		
Travel	FAIR · Attn		
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN · (FAIR) · DIRTY		
Operator's Seat	FAIR · (Attn)	汚れあり DIRTY	
Glasses	FAIR · Attn		
AirCon	A/C · H/C · (H only) · C only · None		
BLADE & CYLINDERS			
BLADE	FAIR · Attn		
CYLD.(R)	FAIR · Attn		
CYLD.(L)	FAIR · Attn		
TILT CYLD	FAIR · Attn		
ANGLE CYLD	FAIR · Attn		
UNDERCARRIAGE		See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3	
COMMENT			
下周り油漏れあり(吸着マット付)			
BOTTOM: OIL LEAKING (W/ABSORPTION MAT)			
Ripper	MULTI · S/S	Shanks	PCS
Ripper CYLD.	FAIR · Attn		
COMMENT			
機体外装リペイントあり REPAINTED			
ヒーター故障あり HEATER: MALFUNCTION			
ラジオ故障あり RADIO: MALFUNCTION			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。