

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2026/7/13	MAKE	mitsubishi	MODEL	BD2F
SERIAL	1B100370			STAMP	1B100370
HR METER	4931	HR	SHOE	300G	YEAR YR
BLADE	STRAIGHT / ST/TILT / PAT / ANGLE / OTHER			CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE

ENGINE : MODEL		S/N	6080
Oil leakage	FAIR	Attn	
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
US EPA	YES	NO	
OPERATION PUMP			
Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	
COOLING SYSTEM			
Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	
TRANSMISSION & TRAVEL			
T/M TYPE	PS	DD	DIFF. STEERING YES · NO
Transmission	FAIR	Attn	
Travel	FAIR	Attn	*1
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN	FAIR	DIRTY
Operator's Seat	FAIR	Attn	
Glasses	FAIR	Attn	
AirCon	A/C	H/C	H only · C only · None
BLADE & CYLINDERS			
BLADE	FAIR	Attn	
CYLD.(R)	FAIR	Attn	
CYLD.(L)	FAIR	Attn	
TILT CYLD	FAIR	Attn	
ANGLE CYLD	FAIR	Attn	

UNDERCARRIAGE See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			2
COMMENT			
両側スプロケット摩耗あり SPROCKETS: WORN			
両側ピンブッシュ摩耗あり PIN BUSHES: WORN			
Ripper	MULTI	S/S	Shanks PCS
Ripper CYLD.	FAIR	Attn	
COMMENT			
*1 左足全くステアリング切れない LEFT TRACK: NOT MOVING			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。