

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2026/7/16	MAKE	CAT	MODEL	D6TLGP-19A
SERIAL	CAT00D6TASGZ00289			STAMP	CAT00D6TASGZ00289
HR METER	13118	HR	SHOE	1000LGP	YEAR YR
BLADE	STRAIGHT / <u>ST/TILT</u> / PAT / ANGLE / OTHER			CAB/CNP	<u>ROPS CAB</u> / CAB / ROPS CNP / CNP / NONE

ENGINE : MODEL C9.3		S/N SYE04440
Oil leakage	<u>FAIR</u> · Attn	
Blow-By	<u>FAIR</u> · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<u>FAIR</u> · Attn	
Oil	<u>FAIR</u> · Attn	
Exhaust Color	<u>FAIR</u> · Attn	
US EPA	<u>YES</u> · NO	
OPERATION PUMP		
Sound	<u>FAIR</u> · Attn	
Oil leakage	<u>FAIR</u> · Attn	
Power	<u>FAIR</u> · Attn	
COOLING SYSTEM		
Radiator	<u>FAIR</u> · Attn	
Oil Cooler	<u>FAIR</u> · Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	<u>PS</u> · DD	DIFF. STEERING <u>YES</u> · NO
Transmission	<u>FAIR</u> · Attn	
Travel	<u>FAIR</u> · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · <u>FAIR</u> · DIRTY	
Operator's Seat	<u>FAIR</u> · Attn	
Glasses	<u>FAIR</u> · Attn	
AirCon	<u>A/C</u> · H/C · H only · C only · None	
BLADE & CYLINDERS		
BLADE	<u>FAIR</u> · Attn	
CYLD.(R)	<u>FAIR</u> · Attn	
CYLD.(L)	<u>FAIR</u> · Attn	
TILT CYLD	<u>FAIR</u> · Attn	
ANGLE CYLD	<u>FAIR</u> · Attn	

UNDERCARRIAGE See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			4
COMMENT			
Ripper	MULTI · S/S	Shanks	PCS
Ripper CYLD.	<u>FAIR</u> · Attn		
COMMENT			
CAB内ステッカーのE/Gナンバーが違う			
ENGINE No.: NOT EQUAL BETWEEN STICKER ON ENGINE & STICKER IN CAB			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。