

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2026/7/21	MAKE	KAWASAKI	MODEL	70ZV
SERIAL	70H4-0300	STAMP	70H4-0300		
HR METER	16197	HR	Odometer	44184	km
CAB/CNP	ROPS CAB / CAB	ROPS CNP / CNP / NONE	TIRE SIZE	20.5-25	YEAR

ENGINE : MODEL J08C S/N UD11476	
Oil leakage	FAIR • ☒ Attn *1
Blow-By	FAIR • Attn A LITTLE • MIDDLE • SEVERE
Sound	FAIR • Attn
Oil	FAIR • Attn
Exhaust Color	FAIR • Attn
US EPA	YES • ☒ NO
OPERATION PUMP	
Sound	FAIR • Attn
Oil leakage	FAIR • ☒ Attn 油漏れ小 OIL LEAKING
Power	FAIR • Attn
COOLING SYSTEM	
Radiator	FAIR • Attn
Oil Cooler	FAIR • Attn
TRANSMISSION & TRAVEL	
T/M TYPE	PS • ☒ DD
Transmission	FAIR • Attn
Travel	FAIR • Attn
FOOT BRAKE	FAIR • Attn
PARKING BRAKE	FAIR • Attn
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN • ☒ FAIR • DIRTY
Operator's Seat	FAIR • Attn 破れあり TORN
Glasses	FAIR • Attn
AirCon	A/C • H/C • H only • C only • None
FRONT & CYLINDERS	
Arm	FAIR • Attn
Bell crank	FAIR • Attn
Bucket	FAIR • ☒ Attn *2
Articulate	FAIR • ☒ Attn *3

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
TIRE WEAR	☒ FAIR • ☐ WORN • ☐ UNEVEN WEAR
COMMENT	
STEERING TYPE ☒ WHEEL STEERING / ☐ COMMAND STEERING / ☐ LEVER STEERING	
RIDE CONTROL	YES • ☒ NO
ATTACHMENTS	
STD BKT	☒ YES • ☐ OTHER
BLADE	YES • ☒ NO Piping for Tilt YES • ☒ NO
COMMENT	
コントロールバルブにじみあり CONTROL VALVE: OIL OOZING	
オイルフィルター油漏れあり OIL FILTER: OIL LEAKING	
リペイントあり REPAINTED	
左CABドア下側ラッチ不良 LOWER LEFT DOOR LATCH: MALFUNCTION	
バッテリーランプ点灯あり BATTERY WARNING LAMP: ON	
作動油温メーター振り切る(センサー不良?)	
HYDRAULIC OIL TEMPERATURE GAUGE: MAXED OUT	
(SENSOR: MALFUNCTION?)	
A/Cベルト鳴きあり A/C BELT: NOISES	
*1 アクセル周りにじみあり AROUND ACCELERATOR: OIL OOZING	
*2 シリンダー油漏れ、バケット穴あり	
*2 CYLINDER: OIL LEAKING, BUCKET: MUCH HUGE HOLES	
*3 左右シリンダーにじみ、左シリンダーホース油漏れあり	
*3 CYLINDERS: OIL OOZING, LEFT CYLINDER HOSE: OIL LEAKING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
1	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。