

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2026/7/17	MAKE	MITSUBISHI	MODEL	BD2J
SERIAL	JB610214			STAMP	2B610214
HR METER	2573	HR	SHOE	450R	YEAR YR
BLADE	STRAIGHT / ST/TILT / PAT / ANGLE / OTHER			CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE

ENGINE : MODEL		S/N	83416
Oil leakage	☒ FAIR	Attn	
Blow-By	☒ FAIR	Attn A LITTLE · MIDDLE · SEVERE	
Sound	☒ FAIR	Attn	
Oil	☒ FAIR	Attn	
Exhaust Color	☒ FAIR	Attn	
US EPA	YES	☒ NO	
OPERATION PUMP			
Sound	☒ FAIR	Attn	
Oil leakage	☒ FAIR	Attn	
Power	☒ FAIR	Attn	
COOLING SYSTEM			
Radiator	☒ FAIR	Attn	
Oil Cooler	☒ FAIR	Attn	
TRANSMISSION & TRAVEL			
T/M TYPE	☒ PS	DD	DIFF. STEERING YES ☒ NO
Transmission	☒ FAIR	Attn	
Travel	☒ FAIR	Attn	
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN	☒ FAIR	DIRTY
Operator's Seat	☒ FAIR	Attn	
Glasses	☒ FAIR	Attn	
AirCon	A/C	H/C	H only · C only ☒ None
BLADE & CYLINDERS			
BLADE	☒ FAIR	Attn	
CYLD.(R)	☒ FAIR	Attn	
CYLD.(L)	☒ FAIR	Attn	
TILT CYLD	☒ FAIR	Attn	
ANGLE CYLD	☒ FAIR	Attn 左側油漏れあり LEFT CYLINDER: OIL LEAKING	

UNDERCARRIAGE See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			2
COMMENT			
Ripper MULTI · S/S Shanks PCS Ripper CYLD. FAIR · Attn			
COMMENT			
安全レバー破損あり SAFETY LEVER: BROKEN			
右側走行レバー戻り悪い RIGHT TRAVEL LEVER: HARD TO RETURN			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。