

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2026/7/13	MAKE	KOMATSU	MODEL	SD23-6
SERIAL	85916			STAMP	M187-85916
HR METER	6878	HR	Odometer	-	km
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP			TIRE SIZE	F: 8.25-20 R: 7.50-16

ENGINE : MODEL 6D102E-2 S/N Oil leakage ☒ FAIR · Attn Blow-By ☒ FAIR · Attn A LITTLE · MIDDLE · SEVERE Sound ☒ FAIR · Attn Oil ☒ FAIR · Attn Exhaust Color ☒ FAIR · Attn US EPA YES · ☒ NO OPERATION PUMP Sound ☒ FAIR · Attn Oil leakage ☒ FAIR · Attn Power ☒ FAIR · Attn COOLING SYSTEM Radiator ☒ FAIR · Attn Oil Cooler ☒ FAIR · Attn TRANSMISSION & TRAVEL T/M TYPE ☒ PS · DD Transmission ☒ FAIR · Attn Travel ☒ FAIR · Attn FOOT BRAKE ☒ FAIR · Attn PARKING BRAKE ☒ FAIR · Attn INTERIOR See Photos. 写真参照 INTERIOR COND. CLEAN · ☒ FAIR · DIRTY Operator's Seat FAIR · ☒ Attn 切れあり CUTS Glasses FAIR · Attn AirCon A/C · H/C · H only · C only · ☒ None FRONT & CYLINDERS Arm ☒ FAIR · Attn Bell crank ☒ FAIR · Attn Bucket ☒ FAIR · Attn Articulate ☒ FAIR · Attn	UNDERCARRIAGE : See Photos. 写真参照 RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3 TIRE WEAR ☒ FAIR · WORN · UNEVEN WEAR COMMENT STEERING TYPE ☒ WHEEL STEERING / ☐ COMMAND STEERING / ☐ LEVER STEERING RIDE CONTROL YES · ☒ NO ATTACHMENTS STD BKT ☒ YES · OTHER BLADE YES · ☒ NO Piping for Tilt YES · ☒ NO COMMENT RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3
---	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。