

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/7/13	MAKE	KOMATSU	MODEL	PC400ST-6
SERIAL	10025			STAMP	NOT FOUND
HR METER	UNREADABLE		HR	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	700G

ENGINE : MODEL		6D125E-2		S/N	
Oil leakage	FAIR	Attn	油汚れあり OIL STAINS		
Blow-By	FAIR	Attn	A LITTLE ・ MIDDLE ・ SEVERE		
Sound	FAIR	Attn			
Oil	FAIR	Attn			
Exhaust Color	FAIR	Attn			
US EPA	YES	NO			
MAIN PUMP					
Sound	FAIR	Attn			
Oil leakage	FAIR	Attn			
Power	FAIR	Attn			
COOLING SYSTEM					
Radiator	FAIR	Attn			
Oil Cooler	FAIR	Attn			
OPERATING SYSTEM					
Swing	FAIR	Attn			
Travel	FAIR	Attn			
INTERIOR		See Photos. 写真参照			
INTERIOR COND.	CLEAN	FAIR	DIRTY		
Operator's Seat	FAIR	Attn			
Glasses	FAIR	Attn			
AirCon	A/C	H/C	H only	C only	None
BOOM / ARM / BKT					
Boom	FAIR	Attn			
Boom Cylinder	FAIR	Attn			
Arm	FAIR	Attn			
Arm Cylinder	FAIR	Attn			
ATTACHMENT	FAIR	Attn	Hリンク、Iリンクなし H-LINK & I-LINKS: NOTHING		
BKT Cylinder	FAIR	Attn			
UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3
COMMENT					
BKT	STD / SLOPE / NARROW / SKELETON / OTHER()				
Lever	LONG	WRIST			
Multi	MULTI	2	NO		
ARM-CRANE	YES	NO			
BLADE	YES	NO			
OFFSET	YES	NO			
OFFSET Cylinder	FAIR	Attn			
Piping	YES	NO	Breaker only	Multi	
COMMENT					
ショートリーチ SHORT REACH					
アタッチメントなし WITHOUT ATTACHMENT					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。