

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/9/10	MAKE	KUBOTA	MODEL	RX-303S
SERIAL	60975		STAMP	60975	
HR METER	4301	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	300R	

ENGINE : MODEL		S/N	6N0594	
Oil leakage	FAIR	Attn		
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR	Attn		
Oil	FAIR	Attn		
Exhaust Color	FAIR	Attn		
US EPA	YES	NO		
MAIN PUMP				
Sound	FAIR	Attn		
Oil leakage	FAIR	Attn		
Power	FAIR	Attn		
COOLING SYSTEM				
Radiator	FAIR	Attn		
Oil Cooler	FAIR	Attn		
OPERATING SYSTEM				
Swing	FAIR	Attn		
Travel	FAIR	Attn		
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN	FAIR	DIRTY	
Operator's Seat	FAIR	Attn		
Glasses	FAIR	Attn		
AirCon	A/C	H/C	H only	C only · None
BOOM / ARM / BKT				
Boom	FAIR	Attn		
Boom Cylinder	FAIR	Attn		
Arm	FAIR	Attn	ガタあり LOOSE	
Arm Cylinder	FAIR	Attn		
ATTACHMENT	FAIR	Attn	コンクリ付着あり CONCRETE STAINS	
BKT Cylinder	FAIR	Attn		

UNDERCARRIAGE :		See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3
COMMENT			
右シュー切り傷、亀裂大 RIGHT RUBBER TRACK: TOO MUCH CRACKED			
下周り油漏れ小 BOTTOM: OIL LEAKING			
BKT	STD	SLOPE / NARROW / SKELETON / OTHER()	
Lever	LONG	WRIST	
Multi	MULTI	2	NO *1
ARM-CRANE	YES	NO	
BLADE	YES	NO	
OFFSET	YES	NO	
OFFSET Cylinder	FAIR	Attn	
Piping	YES	NO	Breaker only Multi
COMMENT			
操作バルブ周り油漏れ小 AROUND OPERATING VALVE: OIL LEAKING			
付属品: フォークブラブ FORK GRAB AS SPARE			
*1 マルチ切り替えカバー欠品 2-WAY LEVER COVER: MISSING			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。