

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2026/7/23	MAKE	KAWASAKI	MODEL	70ZV
SERIAL	70H4-0387			STAMP	70H4-0387
HR METER	4098	HR	Odometer	20737	km
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	20.5-25

ENGINE : MODEL		J08C	S/N	UD12008
Oil leakage	☒ FAIR	Attn		
Blow-By	☒ FAIR	A LITTLE · MIDDLE · SEVERE		
Sound	☒ FAIR	Attn		
Oil	☒ FAIR	Attn		
Exhaust Color	☒ FAIR	Attn		
US EPA	YES	☒ NO		
OPERATION PUMP				
Sound	☒ FAIR	Attn		
Oil leakage	☒ FAIR	Attn		
Power	☒ FAIR	Attn		
COOLING SYSTEM				
Radiator	☒ FAIR	Attn		
Oil Cooler	☒ FAIR	Attn		
TRANSMISSION & TRAVEL				
T/M TYPE	☒ PS	☐ DD		
Transmission	☒ FAIR	Attn		
Travel	☒ FAIR	Attn		
FOOT BRAKE	☒ FAIR	Attn		
PARKING BRAKE	☒ FAIR	Attn		
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN	☒ FAIR		DIRTY
Operator's Seat	☒ FAIR	Attn 破れあり CUTS		
Glasses	☒ FAIR	Attn		
AirCon	☒ A/C	☐ H/C · ☐ H only · ☐ C only · ☐ None		
FRONT & CYLINDERS				
Arm	☒ FAIR	Attn		
Bell crank	☒ FAIR	Attn		
Bucket	FAIR	Attn *1		
Articulate	FAIR	Attn *2		

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	FAIR · ☒ WORN · UNEVEN WEAR
COMMENT	
STEERING TYPE ☒ WHEEL STEERING / ☐ COMMAND STEERING / ☐ LEVER STEERING	
RIDE CONTROL	YES · ☒ NO
ATTACHMENTS	
STD BKT	YES · ☒ OTHER スノーブレード SNOW BLADE
BLADE	YES · ☒ NO Piping for Tilt ☒ YES · ☐ NO
COMMENT	
コントロールバルブ油漏れ小 CONTROL VALVE: OIL LEAKING	
コントロールバルブ周りホースにじみあり	
SOME HOSE AROUND CONTROL VALVE: OIL OOZING	
CAB下にじみあり BOTTOM OF CAB: OIL OOZING	
オイルフィルターにじみあり OIL FILTER: OIL OOZING	
*1 右アングルシリンダーにじみあり RIGHT ANGLE CYLINDER: OIL OOZING	
*2 左シリンダー油漏れあり、右側油漏れ小 CYLINDERS: OIL LEAKING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。