

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2026/7/16	MAKE	KAWASAKI	MODEL	70ZA
SERIAL	70J1-1885		STAMP	70J1-1885	
HR METER	4886	HR	Odometer	-	km
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		TIRE SIZE	20.5-25	

ENGINE : MODEL 6BG1 S/N 151164	
Oil leakage	FAIR · Attn
Blow-By	FAIR · Attn A LITTLE MIDDLE SEVERE
Sound	FAIR · Attn
Oil	FAIR · Attn
Exhaust Color	FAIR · Attn 黒煙小 A LITTLE BLACK FUMES
US EPA	YES · NO
OPERATION PUMP	
Sound	FAIR · Attn
Oil leakage	FAIR · Attn
Power	FAIR · Attn
COOLING SYSTEM	
Radiator	FAIR · Attn
Oil Cooler	FAIR · Attn
TRANSMISSION & TRAVEL	
T/M TYPE	PS · DD
Transmission	FAIR · Attn
Travel	FAIR · Attn
FOOT BRAKE	FAIR · Attn
PARKING BRAKE	FAIR · Attn
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · FAIR · DIRTY
Operator's Seat	FAIR · Attn 破れあり CUTS
Glasses	FAIR · Attn
AirCon	A/C · H/C · H only · C only · None
FRONT & CYLINDERS	
Arm	FAIR · Attn
Bell crank	FAIR · Attn
Bucket	FAIR · Attn
Articulate	FAIR · Attn *1

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
TIRE WEAR	FAIR · WORN · UNEVEN WEAR
COMMENT	
STEERING TYPE WHEEL STEERING / COMMAND STEERING / LEVER STEERING	
RIDE CONTROL	YES · NO
ATTACHMENTS	
STD BKT	YES OTHER マルチプラウ MULTI PLOW
BLADE	YES · NO Piping for Tilt YES · NO
COMMENT	
ワンタッチ付 W/ONE-TOUCH	
マルチプラウ左側アングルシリンダー油漏れあり	
LEFT ANGLE CYLINDER OF MULTI PLOW: OIL LEAKING	
*1 右側シリンダー油漏れあり RIGHT CYLINDER: OIL LEAKING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。