

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2026/7/16	MAKE	KAWASAKI	MODEL	65ZV-D		
SERIAL	65C4-0409			STAMP	65C4-0409		
HR METER	2978	HR	Odometer	21598	km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	17.5-25		

ENGINE :	MODEL	6B5.9	S/N	26397410
Oil leakage	FAIR · Attn			
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE		
Sound	FAIR · Attn			
Oil	FAIR · Attn			
Exhaust Color	FAIR · Attn			
US EPA	YES · NO			

OPERATION PUMP

Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	

COOLING SYSTEM

Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	

TRANSMISSION & TRAVEL

T/M TYPE	PS · DD	
Transmission	FAIR · Attn	
Travel	FAIR · Attn	
FOOT BRAKE	FAIR · Attn	
PARKING BRAKE	FAIR · Attn	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN ▪ FAIR ▪ DIRTY				
Operator's Seat	FAIR	▪ Attn			
Glasses	FAIR	▪ Attn			
AirCon	A/C	▪	H/C	▪ H only	▪ C only ▪ None

FRONT & CYLINDERS

Arm	FAIR	Attn	
Bell crank	FAIR	Attn	
Bucket	FAIR	Attn	
Articulate	FAIR	Attn	左側にじみあり LEFT CYLINDER: OIL OOZING

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
---	----------

TIRE WEAR (FAIR - WORN - UNEVEN WEAR)

COMMENT

STEERING TYPE ☒ WHEEL STEERING / ☐ COMMAND STEERING / ☐ LEVER STEERING

RIDE CONTROL	YES	☒ NO
--------------	-----	-------------------------------------

ATTACHMENTS

STD BKT	YES	OTHER	スノーブレード SNOW BLADE
BLADE	YES	NO	Piping for Tilt YES NO

COMMENT

CAB下油漏れあり BOTTOM OF CAB: OIL LEAKING
コントロールバルブホースにじみあり
SOME CONTROL VALVE HOSES: OIL OOZING

This image shows a blank sheet of white paper with horizontal ruling lines. The lines are evenly spaced and extend across the width of the page. On the left side, there is a vertical margin line, creating a narrow left margin. The paper appears to be from a notebook or a standard ruled document.[illegible]

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) **2**

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。