

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/8/7	MAKE	HITACHI	MODEL	ZX225USR-5B
SERIAL	HCMDCQA0E00304757			STAMP	HCMDCQA0E00304757
HR METER	10156	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	600G

ENGINE : MODEL		S/N
Oil leakage	FAIR	Attn
Blow-By	FAIR	Attn
Sound	FAIR	Attn
Oil	FAIR	Attn
Exhaust Color	FAIR	Attn
US EPA	YES	NO
MAIN PUMP		
Sound	FAIR	Attn
Oil leakage	FAIR	Attn
Power	FAIR	Attn
COOLING SYSTEM		
Radiator	FAIR	Attn
Oil Cooler	FAIR	Attn
OPERATING SYSTEM		
Swing	FAIR	Attn
Travel	FAIR	Attn
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN	FAIR
Operator's Seat	FAIR	Attn
Glasses	FAIR	Attn
AirCon	A/C	H/C H only C only None
BOOM / ARM / BKT		
Boom	FAIR	Attn
Boom Cylinder	FAIR	Attn
Arm	FAIR	Attn
Arm Cylinder	FAIR	Attn
ATTACHMENT	FAIR	Attn
BKT Cylinder	FAIR	Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
BKT (STD / SLOPE / NARROW / SKELETON / OTHER ())	
Lever	LONG WRIST
Multi	MULTI 2 NO
ARM-CRANE	YES NO
BLADE	YES NO
OFFSET	YES NO
OFFSET Cylinder	FAIR Attn
Piping	YES NO Breaker only Multi
COMMENT	
A/Cベルト鳴きあり A/C BELT: NOISES	
左サイドカバー変形あり、完全には閉まらない	
LEFT SIDE COVER: DISTORTED, UNABLE TO SHUT COMPLETELY	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。