

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/7/30	MAKE	KOBELCO	MODEL	SK130UR-1ES
SERIAL	YX05-02150			STAMP	YX05-02150
HR METER	11853	HR	YEAR	2007	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	500G PADS

ENGINE : MODEL		4BG1	S/N	928116	
Oil leakage	FAIR	Attn			
Blow-By	FAIR	Attn	A LITTLE ・ MIDDLE ・ SEVERE		
Sound	FAIR	Attn			
Oil	FAIR	Attn			
Exhaust Color	FAIR	Attn			
US EPA	YES	NO			
MAIN PUMP					
Sound	FAIR	Attn			
Oil leakage	FAIR	Attn			
Power	FAIR	Attn			
COOLING SYSTEM					
Radiator	FAIR	Attn			
Oil Cooler	FAIR	Attn			
OPERATING SYSTEM					
Swing	FAIR	Attn	動き若干遅い A LITTLE SLOW MOVING		
Travel	FAIR	Attn	HI/LO切替え不良 HI/LO SWITCH: MALFUNCTION		
INTERIOR See Photos. 写真参照					
INTERIOR COND.	CLEAN	FAIR	DIRTY		
Operator's Seat	FAIR	Attn	破れあり CUTS		
Glasses	FAIR	Attn	天窓割れあり SKYLIGHT: CRACKED		
AirCon	A/C	H/C	H only	C only	None
BOOM / ARM / BKT					
Boom	FAIR	Attn			
Boom Cylinder	FAIR	Attn	*1		
Arm	FAIR	Attn	ガタあり LOOSE		
Arm Cylinder	FAIR	Attn	油漏れあり OIL LEAKING		
ATTACHMENT	FAIR	Attn			
BKT Cylinder	FAIR	Attn	油漏れ小 OIL LEAKING		

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
スイベル下油漏れあり BOTTOM OF SWIVEL: OIL LEAKING	
BKT	STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · WRIST
Multi	MULTI · 2 · NO
ARM-CRANE	YES · NO *2
BLADE	YES · NO
OFFSET	YES · NO ガタあり LOOSE
OFFSET Cylinder	FAIR · Attn
Piping	YES · NO Breaker only · Multi
COMMENT	
A/C効かない A/C: MALFUNCTION	
*1 右油漏れ小、左にじみあり	
*1 RIGHT CYLINDER: OIL LEAKING, LEFT CYLINDER: OIL OOZING	
*2 「干渉防止作動しません」メッセージでモード表示されない	
*2 CRANE MODE: NOT DISPLAYING	
("ANTI-INTERFERENCE SYSTEM: NOT WORKING" DISPLAY)	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。