

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/8/6	MAKE	TADANO	MODEL	TR-350M-3
SERIAL No.	PLATE : 506128			STAMP : TR352-0127	
HR METER	UNKNOWN		HR	Odometer	UNKNOWN km
TIRE SIZE	445/95R25			YEAR	YR

ENGINE : MODEL S/N

Oil leakage	FAIR	Attn	E/Gヘッド油漏れあり CYLINDER HEAD: OIL LEAKING
Blow-By	FAIR	Attn	A LITTLE MIDDLE SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	

OPERATION PUMP

Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	

COOLING SYSTEM

Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	

OPERATING SYSTEM

Computer	OK	NG	
Swing	FAIR	Attn	
Travel	FAIR	Attn	

TRANSMISSION

Transmission	FAIR	Attn	
No. OF GEARS	4	GEARS	
4WD	4WD	6WD	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN	FAIR	DIRTY
Operator's Seat	FAIR	Attn	破れあり HUGE CUTS
Glasses	FAIR	Attn	
AirCon	A/C	H/C	H only C only None

COMMENT

BOOM

No. of Section	5	SECTIONS	
CRACK/ENFORCEMENT	FAIR	Attn	
DERRICKING CYL.	FAIR	Attn	
EXTENSION CYL.	FAIR	Attn	油漏れあり OIL LEAKING
JIB	YES	NO	
JIB TYPE	STD	PWR	
MAIN & SUB WIRE	YES	NO	
FREE FALL	YES	NO	
HOOK	35t, 20t, BALL		

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1
TIRE WEAR	FAIR WORN UNEVEN WEAR

COMMENT

左Fサスシリンダー油漏れあり
FRONT LEFT SUSPENSION CYLINDER: OIL LEAKING

OUTRIGGERS

OUTRIGGERS	X	H	
OUTRIGGERS COND.	FAIR	Attn	
Oil leakage (JACK CYL.)	FRONT	L R	REAR L R
Oil leakage (SLIDE CYL.)	FRONT	L R	REAR L R

COMMENT

メーター交換歴あり METERS: REPLACED	
エアー漏れあり AIR LEAKING	
ブーム伸縮時ペダルで操作	
NEED TO OPERATE TO TELESCOPE BOOM BY PEDAL	
フットブレーキ効きが悪い FOOT BRAKE: LOOSE	
35tフック、ジブ:別置き 35t HOOK & JIB: NOT ATTACHED	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。