

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2026/7/27	MAKE	KOMATSU	MODEL	D31P-18
SERIAL	44016			STAMP	44016
HR METER	E2772	HR	SHOE	600LGP	YEAR YR
BLADE	STRAIGHT / ST/TILT / PAT / ANGLE / OTHER			CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE

ENGINE : MODEL		6D95L-1	S/N	91852
Oil leakage	FAIR · Attn			
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE		
Sound	FAIR · Attn			
Oil	FAIR · Attn			
Exhaust Color	FAIR · Attn			
US EPA	YES · NO			

OPERATION PUMP

Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	

COOLING SYSTEM

Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	

TRANSMISSION & TRAVEL

T/M TYPE	PS · DD	DIFF. STEERING	YES · NO
Transmission	FAIR · Attn		
Travel	FAIR · Attn		

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN • FAIR • DIRTY	
Operator's Seat	FAIR • Attn	破れあり TORN
Glasses	FAIR • Attn	
AirCon	A/C • H/C • H only • C only • None	

BLADE & CYLINDERS

BLADE	FAIR	Attn	
CYLD.(R)	FAIR	Attn	
CYLD.(L)	FAIR	Attn	
TILT CYLD	FAIR	Attn	
ANGLE CYLD	FAIR	Attn	

UNDERCARRIAGE See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
---	----------

COMMENT

左シューリンク固着あり LEFT TRACK LINKS: STUCK

Ripper	MULTI ▪ S/S	Shanks	PCS
--------	-------------	--------	-----

Ripper CYLD.	FAIR ▪ Attn	
--------------	-------------	--

COMMENT

全体的にホースひび割れあり MANY HOSES: MUCH CRACKED

EGRコントローラー電源入らない EGR CONTROLLER: UNABLE TO TURN ON

HRメーターストップ HR METER: STOPPED

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
---	----------

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。