

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/9/2	MAKE	YANMAR	MODEL	VIO30-6
SERIAL	6J917		STAMP	6J917	
HR METER	1949	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	300G PADS	

ENGINE : MODEL		S/N	155107
Oil leakage	(FAIR) · Attn		
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	(FAIR) · Attn		
Oil	(FAIR) · Attn		
Exhaust Color	(FAIR) · Attn		
US EPA	YES · (NO)		
MAIN PUMP			
Sound	(FAIR) · Attn		
Oil leakage	(FAIR) · Attn		
Power	(FAIR) · Attn		
COOLING SYSTEM			
Radiator	(FAIR) · Attn		
Oil Cooler	(FAIR) · Attn		
OPERATING SYSTEM			
Swing	(FAIR) · Attn		
Travel	(FAIR) · Attn		
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN · (FAIR) · DIRTY		
Operator's Seat	FAIR · (Attn)	破れあり CUTS	
Glasses	FAIR · Attn		
AirCon	A/C · H/C · H only · C only · (None)		
BOOM / ARM / BKT			
Boom	(FAIR) · Attn		
Boom Cylinder	(FAIR) · Attn		
Arm	(FAIR) · Attn		
Arm Cylinder	(FAIR) · Attn		
ATTACHMENT	(FAIR) · Attn		
BKT Cylinder	(FAIR) · Attn		

UNDERCARRIAGE :		See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			4
COMMENT			
BKT	(STD)	SLOPE / NARROW / SKELETON / OTHER()	
Lever	LONG · (WRIST)		
Multi	(MULTI) · 2 · NO		
ARM-CRANE	YES · (NO)		
BLADE	(YES) · NO		
OFFSET	YES · (NO)		
OFFSET Cylinder	FAIR · Attn		
Piping	(YES) · NO	Breaker only · (Multi)	
COMMENT			
燃料ゲージ不良(ステッカーあり)			
FUEL GAUGE: MALFUNCTION (W/NOTE)			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。