

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/7/17	MAKE	KOMATSU	MODEL	PC228US-3E0
SERIAL	40823			STAMP	KMTPC161J02040823
HR METER	9706	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	600G

ENGINE : MODEL 6D107E-1 S/N 26509944	
Oil leakage	FAIR • Attn
Blow-By	FAIR • Attn A LITTLE • MIDDLE • SEVERE
Sound	FAIR • Attn
Oil	FAIR • Attn
Exhaust Color	FAIR • Attn
US EPA	YES • NO
MAIN PUMP	
Sound	FAIR • Attn
Oil leakage	FAIR • Attn
Power	FAIR • Attn
COOLING SYSTEM	
Radiator	FAIR • Attn
Oil Cooler	FAIR • Attn
OPERATING SYSTEM	
Swing	FAIR • Attn ガタあり SWING: LOOSE
Travel	FAIR • Attn
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN • FAIR • DIRTY
Operator's Seat	FAIR • Attn 破れあり TORN
Glasses	FAIR • Attn
AirCon	A/C • H/C • H only • C only • None
BOOM / ARM / BKT	
Boom	FAIR • Attn 本体側補修跡あり BODY SIDE: REPAIRED
Boom Cylinder	FAIR • Attn
Arm	FAIR • Attn ガタあり LOOSE
Arm Cylinder	FAIR • Attn
ATTACHMENT	FAIR • Attn ガタあり LOOSE
BKT Cylinder	FAIR • Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
BKT (STD / SLOPE / NARROW / SKELETON / OTHER ())	
Lever	LONG • WRIST
Multi	MULTI • 2 • NO
ARM-CRANE	YES • NO *1
BLADE	YES • NO
OFFSET	YES • NO
OFFSET Cylinder	FAIR • Attn
Piping	YES • NO Breaker only • Multi
COMMENT	
ブーム下ホース破れあり	
MANY HOSES AROUND LOWER PART OF BOOM: MUCH CRACKED	
エアクリーナー目詰まり警告表示あり	
WARNING LAMP FOR CLOGGING OF AIR CLEANER: ON	
A/Cユニット不良、電源入らない	
A/C UNIT: MALFUNCTION, UNABLE TO TURN ON	
*1 E50エラー表示、ブザー音あり	
*1 "E50" ERROR DISPLAY, WARNING SOUNDS: ON	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。