

INSPECTION SHEET 検品書
CRAWLER CRANE クローラクレーン

INSPECTION DATE	2026/8/6	MAKE	HITACHI	MODEL	CX500
SERIAL No.	PLATE :	243-2011	STAMP	243-2011	
HR METER	19177	HR	SHOE	760FLAT	YEAR YR

ENGINE : MODEL S/N		INTERIOR See Photos. 写真参照	
Oil leakage	FAIR ☒ Attn *1	INTERIOR COND.	CLEAN ☐ FAIR ☒ DIRTY ☐
Blow-By	FAIR ☒ Attn A LITTLE ☐ MIDDLE ☐ SEVERE ☐	Operator's Seat	FAIR ☒ Attn 穴あり HOLES
Sound	FAIR ☒ Attn	Glasses	FAIR ☒ Attn
Oil	FAIR ☒ Attn	AirCon	A/C ☒ H/C ☐ H only ☐ C only ☐ None ☐
Exhaust Color	FAIR ☒ Attn	UNDERCARRIAGE : See Photos. 写真参照	
OPERATION PUMP		RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 2	
Sound	FAIR ☒ Attn	COMMENT	
Oil leakage	FAIR ☒ Attn	左右キャタールみあり TRACK LINKS: WORN	
Power	FAIR ☒ Attn		
COOLING SYSTEM		WEIGHT	2
Radiator	FAIR ☒ Attn	HOOK	50t, 30t, BALL
Oil Cooler	FAIR ☒ Attn	FREE FALL	YES ☒ NO ☐
OPERATING SYSTEM		LIFTER	YES ☐ NO ☒
Computer	OK ☒ NG 未確認 NOT CHECKED	COMMENT	
Swing	FAIR ☒ Attn	ブームサビあり BOOMS: RUSTY	
Travel	FAIR ☒ Attn	*1 ヘッドカバー油漏れあり HEAD COVER: OIL LEAKING	
BOOM			
MAIN BOOM	TOP, BOTTOM, 9m × 2, 6m × 2, 3m × 1	@NARITA YARD	
BOOM TOTAL	43m	BOOM: TOP, BOTTOM, 6m × 1	
		A SET OF WIRE ROPE SOCKETS,	
TOP SHEAVE	YES ☒ NO ☐	@SAKURA YARD	
JIB	15m	BOOM: 9m × 2, 6m × 1, 3m × 1	
TOP, BOTTOM, 3m × 3		HOOK: 30t, BALL	
TOWER		JIB: TOP, BOTTOM, 3m × 3	
		RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 1	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。