

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/7/22	MAKE	HITACHI	MODEL	ZX30U-5B
SERIAL	HCMADHA0T00050095		STAMP	HCMADHA0T00050095	
HR METER	1639	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	300G PADS	

ENGINE : MODEL		S/N
Oil leakage	FAIR	Attn
Blow-By	FAIR	Attn A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn
Oil	FAIR	Attn
Exhaust Color	FAIR	Attn
US EPA	YES	NO
MAIN PUMP		
Sound	FAIR	Attn
Oil leakage	FAIR	Attn
Power	FAIR	Attn
COOLING SYSTEM		
Radiator	FAIR	Attn
Oil Cooler	FAIR	Attn
OPERATING SYSTEM		
Swing	FAIR	Attn
Travel	FAIR	Attn *1
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN	FAIR DIRTY
Operator's Seat	FAIR	Attn フレーム露出あり A LITTLE DAMAGED
Glasses	FAIR	Attn
AirCon	A/C	H/C H only C only None
BOOM / ARM / BKT		
Boom	FAIR	Attn
Boom Cylinder	FAIR	Attn 傷あり SCRATCHED
Arm	FAIR	Attn ガタあり LOOSE
Arm Cylinder	FAIR	Attn にじみあり OIL OOZING
ATTACHMENT	FAIR	Attn ガタあり LOOSE
BKT Cylinder	FAIR	Attn 傷、油漏れあり SCRATCHED, OIL LEAKING

UNDERCARRIAGE :		See Photos. 写真参照
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		2
COMMENT		
BKT	STD	SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG	WRIST
Multi	MULTI	2 · NO
ARM-CRANE	YES	NO
BLADE	YES	NO
OFFSET	YES	NO
OFFSET Cylinder	FAIR	Attn
Piping	YES	NO Breaker only Multi
COMMENT		
リペイントあり REPAINTED		
スパナマークあり MAINTENANCE LAMP: ON		
スイングガタあり SWING PART: LOOSE		
Hリンク補修跡あり H-LINK: REPAIRED		
*1 レバーガタあり、左固着気味 LEVERS: LOOSE, LEFT LEVER: STUCK		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。