

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/8/18	MAKE	TADANO	MODEL	GR-120N-1
SERIAL No.	PLATE : FD0028		STAMP : TR120-0028		
HR METER	15236	HR	Odometer	136975	km
TIRE SIZE	275/80R22.5		YEAR	YR	

ENGINE : MODEL 4M50 S/N

Oil leakage	FAIR	☒ Attn	下部にじみあり BOTTOM OF ENGINE: OIL OOZING
Blow-By	FAIR	☒ Attn	A LITTLE ☒ MIDDLE ☐ SEVERE
Sound	☒ FAIR	☐ Attn	
Oil	☒ FAIR	☐ Attn	
Exhaust Color	☒ FAIR	☐ Attn	

OPERATION PUMP

Sound	FAIR	☒ Attn	
Oil leakage	☒ FAIR	☐ Attn	
Power	☒ FAIR	☐ Attn	

COOLING SYSTEM

Radiator	FAIR	☒ Attn	
Oil Cooler	☒ FAIR	☐ Attn	

OPERATING SYSTEM

Computer	OK	☒ NG	
Swing	☒ FAIR	☐ Attn	
Travel	☒ FAIR	☐ Attn	

TRANSMISSION

Transmission	FAIR	☒ Attn	
No. OF GEARS	3	GEARS	
4WD	☒ 4WD	☐ 6WD	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN	☒ FAIR ☐ DIRTY	
Operator's Seat	☒ FAIR	☐ Attn	破れ、穴あり CUTS, HOLES
Glasses	☒ FAIR	☐ Attn	
AirCon	☒ A/C	☐ H/C	☐ H only ☐ C only ☐ None

COMMENT

BOOM

No. of Section	6	SECTIONS	
CRACK/ENFORCEMENT	☒ FAIR	☐ Attn	
DERRICKING CYL.	☒ FAIR	☐ Attn	
EXTENSION CYL.	☒ FAIR	☐ Attn	
JIB	☒ YES	☐ NO	
JIB TYPE	STD	☒ PWR	
MAIN & SUB WIRE	☒ YES	☐ NO	
FREE FALL	YES	☒ NO	
HOOK	12t, BALL		

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	☒ FAIR ☐ WORN ☐ UNEVEN WEAR

COMMENT

OUTRIGGERS

OUTRIGGERS	☒ X	☐ H	
OUTRIGGERS COND.	☒ FAIR	☐ Attn	
Oil leakage (JACK CYL.)	FRONT	L ☐ R ☐	REAR L ☐ R ☐
Oil leakage (SLIDE CYL.)	FRONT	L ☐ R ☐	REAR L ☐ R ☐

COMMENT

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。