

INSPECTION SHEET 検品書
CRAWLER CRANE クローラクレーン

INSPECTION DATE	2026/7/23	MAKE	MAEDA	MODEL	LC383M-5
SERIAL No.	PLATE :	11216	STAMP	11216	
HR METER	2296	HR	SHOE	300G PADS	YEAR YR

ENGINE : MODEL		S/N
Oil leakage	☒ FAIR · Attn	
Blow-By	☒ FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	☒ FAIR · Attn	
Oil	☒ FAIR · Attn	
Exhaust Color	☒ FAIR · Attn	
OPERATION PUMP		
Sound	☒ FAIR · Attn	
Oil leakage	☒ FAIR · Attn	
Power	☒ FAIR · Attn	
COOLING SYSTEM		
Radiator	☒ FAIR · Attn	
Oil Cooler	☒ FAIR · Attn	
OPERATING SYSTEM		
Computer	☒ OK · NG	
Swing	☒ FAIR · Attn	
Travel	☒ FAIR · Attn	
BOOM		
MAIN BOOM		
BOOM TOTAL		
TOP SHEAVE	YES · ☒ NO	
JIB		
TOWER		

INTERIOR		See Photos. 写真参照	
INTERIOR COND.	CLEAN · ☒ FAIR · DIRTY		
Operator's Seat	☒ FAIR · Attn		
Glasses	☒ FAIR · Attn		
AirCon	A/C · H/C · H only · C only · ☒ None		
UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3
COMMENT			
WEIGHT		-	
HOOK		2.93t	
FREE FALL		YES · ☒ NO	
LIFTER		YES · ☒ NO	
COMMENT			
CNP			
EPA: YES			
4段ブーム 4-SECTION BOOM			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。