

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2026/7/24	MAKE	CAT	MODEL	D5H
SERIAL	2SD04151			STAMP	2SD04151
HR METER	3941	HR	SHOE	860LGP	YEAR YR
BLADE	STRAIGHT (ST/TILT) PAT / ANGLE / OTHER			CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE

<table style="width: 100%;"> <tr> <td style="width: 50%;">ENGINE : MODEL</td> <td style="width: 50%;">S/N</td> </tr> <tr> <td>Oil leakage (FAIR) · Attn</td> <td></td> </tr> <tr> <td>Blow-By (FAIR) · Attn</td> <td>A LITTLE · MIDDLE · SEVERE</td> </tr> <tr> <td>Sound (FAIR) · Attn</td> <td></td> </tr> <tr> <td>Oil (FAIR) · Attn</td> <td></td> </tr> <tr> <td>Exhaust Color (FAIR) · Attn</td> <td></td> </tr> <tr> <td>US EPA YES · (NO)</td> <td></td> </tr> <tr> <td colspan="2">OPERATION PUMP</td> </tr> <tr> <td>Sound (FAIR) · Attn</td> <td></td> </tr> <tr> <td>Oil leakage (FAIR) · Attn</td> <td></td> </tr> <tr> <td>Power (FAIR) · Attn</td> <td></td> </tr> <tr> <td colspan="2">COOLING SYSTEM</td> </tr> <tr> <td>Radiator (FAIR) · Attn</td> <td></td> </tr> <tr> <td>Oil Cooler (FAIR) · Attn</td> <td></td> </tr> <tr> <td colspan="2">TRANSMISSION & TRAVEL</td> </tr> <tr> <td>T/M TYPE PS · (DD)</td> <td>DIFF. STEERING YES · (NO)</td> </tr> <tr> <td>Transmission (FAIR) · Attn</td> <td></td> </tr> <tr> <td>Travel (FAIR) · Attn</td> <td></td> </tr> <tr> <td colspan="2">INTERIOR See Photos. 写真参照</td> </tr> <tr> <td>INTERIOR COND. CLEAN · FAIR · (DIRTY)</td> <td></td> </tr> <tr> <td>Operator's Seat (FAIR) · Attn</td> <td></td> </tr> <tr> <td>Glasses (FAIR) · Attn</td> <td></td> </tr> <tr> <td>AirCon A/C · (H/C) · H only · C only · None</td> <td></td> </tr> <tr> <td colspan="2">BLADE & CYLINDERS</td> </tr> <tr> <td>BLADE (FAIR) · Attn</td> <td></td> </tr> <tr> <td>CYLD.(R) (FAIR) · Attn</td> <td></td> </tr> <tr> <td>CYLD.(L) (FAIR) · Attn</td> <td></td> </tr> <tr> <td>TILT CYLD (FAIR) · Attn</td> <td></td> </tr> <tr> <td>ANGLE CYLD FAIR · Attn</td> <td></td> </tr> </table>	ENGINE : MODEL	S/N	Oil leakage (FAIR) · Attn		Blow-By (FAIR) · Attn	A LITTLE · MIDDLE · SEVERE	Sound (FAIR) · Attn		Oil (FAIR) · Attn		Exhaust Color (FAIR) · Attn		US EPA YES · (NO)		OPERATION PUMP		Sound (FAIR) · Attn		Oil leakage (FAIR) · Attn		Power (FAIR) · Attn		COOLING SYSTEM		Radiator (FAIR) · Attn		Oil Cooler (FAIR) · Attn		TRANSMISSION & TRAVEL		T/M TYPE PS · (DD)	DIFF. STEERING YES · (NO)	Transmission (FAIR) · Attn		Travel (FAIR) · Attn		INTERIOR See Photos. 写真参照		INTERIOR COND. CLEAN · FAIR · (DIRTY)		Operator's Seat (FAIR) · Attn		Glasses (FAIR) · Attn		AirCon A/C · (H/C) · H only · C only · None		BLADE & CYLINDERS		BLADE (FAIR) · Attn		CYLD.(R) (FAIR) · Attn		CYLD.(L) (FAIR) · Attn		TILT CYLD (FAIR) · Attn		ANGLE CYLD FAIR · Attn		<table style="width: 100%;"> <tr> <td colspan="2">UNDERCARRIAGE See Photos. 写真参照</td> </tr> <tr> <td>RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</td> <td>4</td> </tr> <tr> <td colspan="2">COMMENT</td> </tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr> <td>Ripper</td> <td>MULTI · S/S Shanks PCS</td> </tr> <tr> <td>Ripper CYLD.</td> <td>FAIR · Attn</td> </tr> <tr> <td colspan="2">COMMENT</td> </tr> <tr> <td colspan="2">右サイドカバー開かない RIGHT SIDE COVER: UNABLE TO OPEN</td> </tr> <tr> <td colspan="2">クーラー: 風冷えない COOLER: MALFUNCTION</td> </tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr> <td colspan="2">RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</td> </tr> <tr> <td colspan="2">3</td> </tr> </table>	UNDERCARRIAGE See Photos. 写真参照		RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4	COMMENT														Ripper	MULTI · S/S Shanks PCS	Ripper CYLD.	FAIR · Attn	COMMENT		右サイドカバー開かない RIGHT SIDE COVER: UNABLE TO OPEN		クーラー: 風冷えない COOLER: MALFUNCTION																						RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3	
ENGINE : MODEL	S/N																																																																																																														
Oil leakage (FAIR) · Attn																																																																																																															
Blow-By (FAIR) · Attn	A LITTLE · MIDDLE · SEVERE																																																																																																														
Sound (FAIR) · Attn																																																																																																															
Oil (FAIR) · Attn																																																																																																															
Exhaust Color (FAIR) · Attn																																																																																																															
US EPA YES · (NO)																																																																																																															
OPERATION PUMP																																																																																																															
Sound (FAIR) · Attn																																																																																																															
Oil leakage (FAIR) · Attn																																																																																																															
Power (FAIR) · Attn																																																																																																															
COOLING SYSTEM																																																																																																															
Radiator (FAIR) · Attn																																																																																																															
Oil Cooler (FAIR) · Attn																																																																																																															
TRANSMISSION & TRAVEL																																																																																																															
T/M TYPE PS · (DD)	DIFF. STEERING YES · (NO)																																																																																																														
Transmission (FAIR) · Attn																																																																																																															
Travel (FAIR) · Attn																																																																																																															
INTERIOR See Photos. 写真参照																																																																																																															
INTERIOR COND. CLEAN · FAIR · (DIRTY)																																																																																																															
Operator's Seat (FAIR) · Attn																																																																																																															
Glasses (FAIR) · Attn																																																																																																															
AirCon A/C · (H/C) · H only · C only · None																																																																																																															
BLADE & CYLINDERS																																																																																																															
BLADE (FAIR) · Attn																																																																																																															
CYLD.(R) (FAIR) · Attn																																																																																																															
CYLD.(L) (FAIR) · Attn																																																																																																															
TILT CYLD (FAIR) · Attn																																																																																																															
ANGLE CYLD FAIR · Attn																																																																																																															
UNDERCARRIAGE See Photos. 写真参照																																																																																																															
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4																																																																																																														
COMMENT																																																																																																															
Ripper	MULTI · S/S Shanks PCS																																																																																																														
Ripper CYLD.	FAIR · Attn																																																																																																														
COMMENT																																																																																																															
右サイドカバー開かない RIGHT SIDE COVER: UNABLE TO OPEN																																																																																																															
クーラー: 風冷えない COOLER: MALFUNCTION																																																																																																															
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)																																																																																																															
3																																																																																																															

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。