

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/8/5	MAKE	KOMATSU	MODEL	PC120-6E0
SERIAL	73567		STAMP	KMTPC037V02073567	
HR METER	9753	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	700G	

ENGINE : MODEL		S/N	26391892
Oil leakage	FAIR · Attn		
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR · Attn		
Oil	FAIR · Attn		
Exhaust Color	FAIR · Attn		
US EPA	YES · NO		
MAIN PUMP			
Sound	FAIR · Attn		
Oil leakage	FAIR · Attn	*1	
Power	FAIR · Attn		
COOLING SYSTEM			
Radiator	FAIR · Attn		
Oil Cooler	FAIR · Attn		
OPERATING SYSTEM			
Swing	FAIR · Attn		
Travel	FAIR · Attn		
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN · FAIR · DIRTY		
Operator's Seat	FAIR · Attn		
Glasses	FAIR · Attn		
AirCon	A/C · H/C · H only · C only · None		
BOOM / ARM / BKT			
Boom	FAIR · Attn		
Boom Cylinder	FAIR · Attn	右油漏れ小 RIGHT CYLINDER: OIL LEAKING	
Arm	FAIR · Attn	ガタ大、ヘコミあり MUCH LOOSE, MUCH DENT	
Arm Cylinder	FAIR · Attn		
ATTACHMENT	FAIR · Attn		
BKT Cylinder	FAIR · Attn		

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT 右トラックローラーガタあり SOME RIGHT TRACK ROLLER: LOOSE	
BKT	(STD) / SLOPE / NARROW / SKELETON / OTHER()
Lever	LONG ▪ (WRIST)
Multi	(MULTI) ▪ 2 ▪ NO
ARM-CRANE	YES ▪ (NO)
BLADE	YES ▪ (NO)
OFFSET	YES ▪ (NO)
OFFSET Cylinder	FAIR ▪ Attn
Piping	YES ▪ (NO) Breaker only ▪ Multi
COMMENT 11.5mスーパーロング 11.5m SUPER LONG *1 ボルト周りコーキングあり AROUND ONE OF BOLTS: CAULKING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。