

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/7/24	MAKE	KOMATSU	MODEL	PC60-7
SERIAL	55993	STAMP	PC60-55993		
HR METER	4185	HR	YEAR	1998	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	SHOE	450ROAD-LINER		

ENGINE : MODEL		S/N
Oil leakage	FAIR · ☒ Attn	*1
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · ☒ NO	
MAIN PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
OPERATING SYSTEM		
Swing	FAIR · ☒ Attn	*2
Travel	FAIR · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · ☒ DIRTY	
Operator's Seat	FAIR · Attn	
Glasses	FAIR · Attn	
AirCon	A/C · H/C · ☒ H only · C only · None	
BOOM / ARM / BKT		
Boom	FAIR · Attn	
Boom Cylinder	FAIR · Attn	
Arm	FAIR · ☒ Attn	*3
Arm Cylinder	FAIR · Attn	
ATTACHMENT	FAIR · Attn	
BKT Cylinder	FAIR · Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
BKT ☒ STD / SLOPE / NARROW / SKELETON / OTHER () Lever LONG · ☒ WRIST Multi MULTI · 2 · ☒ NO ARM-CRANE YES · ☒ NO BLADE ☒ YES · NO OFFSET YES · ☒ NO OFFSET Cylinder FAIR · Attn Piping ☒ YES · NO Breaker only · Multi *4	
COMMENT	
オイルフィルターにじみあり OIL FILTER: OIL OOZING チェックランプ点灯あり(E/Gオイル量?) WARNING LAMP FOR ENGINE OIL LEVEL?: ON *1 E/Gブロックオイルパン周りにじみあり *1 AROUND ENGINE BLOCK & OIL PAN: OIL OOZING *2 ガタ大、縦ガタあり SWING: MUCH LOOSE, VERTICAL PLAY *3 ヘコミ、穴、スライドアーム: ガタあり(長さ: 7.9m) *3 MUCH DENT, HOLE, SLIDE ARM: LOOSE (LENGTH: 7.9m) *4 バケットシリンダーに分岐して入っているため動作しない *4 NOT WORKING (PIPING: BRANCHING TO THE BUCKET CYLINDER)	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。