

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/7/24	MAKE	KOMATSU	MODEL	PC128US-2E0
SERIAL	9185		STAMP	KMTPC039E01009185	
HR METER	9430	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G	

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	
MAIN PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
OPERATING SYSTEM		
Swing	FAIR · Attn	ガタあり SWING: LOOSE
Travel	FAIR · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · DIRTY	
Operator's Seat	FAIR · Attn	破れあり TORN
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	FAIR · Attn	
Boom Cylinder	FAIR · Attn	右側油漏れ小 RIGHT CYLINDER: OIL LEAKING
Arm	FAIR · Attn	ガタ大 MUCH LOOSE
Arm Cylinder	FAIR · Attn	
ATTACHMENT	FAIR · Attn	
BKT Cylinder	FAIR · Attn	にじみあり OIL OOZING

UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3
COMMENT 右トラックローラーガタあり SOME RIGHT TRACK ROLLERS: LOOSE					
BKT	(STD / SLOPE / NARROW / SKELETON / OTHER()				
Lever	LONG ▪ (WRIST)				
Multi	(MULTI) ▪ 2 ▪ NO				
ARM-CRANE	(YES) ▪ NO				
BLADE	YES ▪ (NO)				
OFFSET	YES ▪ (NO)				
OFFSET Cylinder	FAIR ▪ Attn				
Piping	(YES) ▪ NO	Breaker only ▪ Multi			
COMMENT 燃料フィルター上漏れ小 UPPER PART OF FUEL FILTER: FUEL LEAKING ブーム周りホースひび割れ多数あり SOME HOSES AROUND BOOM: MUCH CRACKED					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。