

INSPECTION SHEET 検品書
LIFTING PLATFORM 高所作業車

INSPECTION DATE	2026/7/24	MAKE	NAGANO	MODEL	NUL090-3
SERIAL No.	PLATE : 9NU30176			STAMP : NU0930176	
HR METER	4122	HR	Odometer	km	YEAR YR
CHASSIS	MODEL -			No. -	
SHOE	300G PADS			TIRE SIZE	
MAX HIGHT	9.1 m			MAX WEIGHT	200 kg

ENGINE : MODEL S/N	
Oil leakage	☒ FAIR · Attn
Blow-By	☒ FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	☒ FAIR · Attn
Oil	☒ FAIR · Attn
Exhaust Color	☒ FAIR · Attn
US EPA	YES ☒ NO
OPERATION PUMP	
Sound	☒ FAIR · Attn
Oil leakage	☒ FAIR · Attn
Power	☒ FAIR · Attn
COOLING SYSTEM	
Radiator	☒ FAIR · Attn
Oil Cooler	☒ FAIR · Attn
TRANSMISSION & TRAVEL	
T/M TYPE	☒ AT · MT No. OF GEARS - GEARS
Transmission	☒ FAIR · Attn
4WD	4WD · 2WD
Travel	☒ FAIR · Attn
Swing	☒ FAIR · Attn
FOOT BRAKE	FAIR · Attn
PARKING BRAKE	FAIR · Attn
BOOM	
No. of Section	2 SECTIONS
DERRICKING CYL.	FAIR · ☒ Attn *1
EXTENSION CYL.	☒ FAIR · Attn

INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · ☒ FAIR · DIRTY
Operator's Seat	FAIR · Attn
Glasses	FAIR · Attn
AirCon	A/C · H/C · H only · C only · ☒ None
UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	FAIR · WORN · UNEVEN WEAR
COMMENT	
首振りガタあり BUCKET SWING: LOOSE	
リペイントあり REPAINTED	
アクセル不良 ACCELERATOR: MALFUNCTION	
*1 第2ブームシリンダーサビあり CYLINDER FOR 2nd BOOM : RUSTY	
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。