

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/7/24	MAKE	KOMATSU	MODEL	PC18MR-3
SERIAL	22828			STAMP	KMTPC206LEE022828
HR METER	1847	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / <u>ROPS CNP</u> / CNP / NONE			SHOE	230R

ENGINE : MODEL S/N Oil leakage FAIR · Attn Blow-By FAIR · Attn Sound FAIR · Attn Oil FAIR · Attn Exhaust Color FAIR · Attn US EPA YES · <u>NO</u> A LITTLE · MIDDLE · SEVERE MAIN PUMP Sound FAIR · Attn Oil leakage FAIR · Attn Power FAIR · Attn COOLING SYSTEM Radiator FAIR · Attn Oil Cooler FAIR · Attn OPERATING SYSTEM Swing FAIR · Attn Travel FAIR · Attn INTERIOR See Photos. 写真参照 INTERIOR COND. CLEAN · <u>FAIR</u> · DIRTY Operator's Seat FAIR · Attn Glasses FAIR · Attn AirCon A/C · H/C · H only · C only · <u>None</u> 破れあり CUTS BOOM / ARM / BKT Boom FAIR · Attn Boom Cylinder FAIR · Attn Arm FAIR · Attn Arm Cylinder FAIR · Attn ATTACHMENT FAIR · Attn BKT Cylinder FAIR · Attn	UNDERCARRIAGE : See Photos. 写真参照 RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3 COMMENT 伸縮OK VARIABLE WIDTH UNDERCARRIAGE BKT <u>STD</u> / SLOPE / NARROW / SKELETON / OTHER () Lever LONG · <u>WRIST</u> Multi MULTI · 2 · <u>NO</u> ARM-CRANE YES · <u>NO</u> BLADE <u>YES</u> · NO OFFSET YES · <u>NO</u> OFFSET Cylinder FAIR · Attn Piping YES · <u>NO</u> Breaker only · Multi COMMENT リペイントあり REPAINTED スイングガタあり SWING PART: LOOSE RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。