

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/7/24	MAKE	HITACHI	MODEL	ZX17U-5A
SERIAL	HCMABAA0A00024991			STAMP	HCMABAA0A00024991
HR METER	2207	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	230G PADS

ENGINE : MODEL 3TNV70 S/N U0169						
Oil leakage	(FAIR)	Attn				
Blow-By	(FAIR)	Attn	A LITTLE · MIDDLE · SEVERE			
Sound	(FAIR)	Attn				
Oil	(FAIR)	Attn				
Exhaust Color	(FAIR)	Attn				
US EPA	YES · (NO)					
MAIN PUMP						
Sound	(FAIR)	Attn				
Oil leakage	(FAIR)	Attn				
Power	(FAIR)	Attn				
COOLING SYSTEM						
Radiator	(FAIR)	Attn				
Oil Cooler	(FAIR)	Attn				
OPERATING SYSTEM						
Swing	(FAIR)	Attn	ガタあり SWING: LOOSE			
Travel	(FAIR)	Attn				
INTERIOR See Photos. 写真参照						
INTERIOR COND.	CLEAN · (FAIR) · DIRTY					
Operator's Seat	(FAIR)	Attn	破れあり CUTS			
Glasses	FAIR	Attn				
AirCon	A/C · H/C · H only · C only · (None)					
BOOM / ARM / BKT						
Boom	(FAIR)	Attn				
Boom Cylinder	(FAIR)	Attn				
Arm	(FAIR)	Attn				
Arm Cylinder	(FAIR)	Attn				
ATTACHMENT	(FAIR)	Attn				
BKT Cylinder	(FAIR)	Attn				
UNDERCARRIAGE : See Photos. 写真参照						
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)						3
COMMENT						
伸縮OK VARIABLE WIDTH UNDERCARRIAGE						
BKT	(STD)	SLOPE / NARROW / SKELETON / OTHER()				
Lever	LONG · (WRIST)					
Multi	(MULTI) · 2 · NO					
ARM-CRANE	YES · (NO)					
BLADE	(YES) · NO					
OFFSET	YES · (NO)					
OFFSET Cylinder	FAIR · Attn					
Piping	(YES) · NO	Breaker only · Multi				
COMMENT						
リペイントあり REPAINTED						
スイングガタあり SWING PART: LOOSE						
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)						3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。