

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

|                 |                                        |      |         |                   |           |
|-----------------|----------------------------------------|------|---------|-------------------|-----------|
| INSPECTION DATE | 2026/7/28                              | MAKE | KOMATSU | MODEL             | PC138US-8 |
| SERIAL          | 28797                                  |      | STAMP   | KMTPC189L01028797 |           |
| HR METER        | UNKNOWN                                |      | HR      | YEAR              | YR        |
| CAB/CNP         | ROPS CAB / CAB / ROPS CNP / CNP / NONE |      | SHOE    | 500G              |           |

|                           |       |                              |                            |        |
|---------------------------|-------|------------------------------|----------------------------|--------|
| ENGINE : MODEL            |       | 4D95LE-5                     | S/N                        | 538748 |
| Oil leakage               | FAIR  | Attn                         |                            |        |
| Blow-By                   | FAIR  | Attn                         | A LITTLE · MIDDLE · SEVERE |        |
| Sound                     | FAIR  | Attn                         |                            |        |
| Oil                       | FAIR  | Attn                         |                            |        |
| Exhaust Color             | FAIR  | Attn                         |                            |        |
| US EPA                    | YES   | NO                           |                            |        |
| MAIN PUMP                 |       |                              |                            |        |
| Sound                     | FAIR  | Attn                         |                            |        |
| Oil leakage               | FAIR  | Attn                         |                            |        |
| Power                     | FAIR  | Attn                         |                            |        |
| COOLING SYSTEM            |       |                              |                            |        |
| Radiator                  | FAIR  | Attn                         |                            |        |
| Oil Cooler                | FAIR  | Attn                         |                            |        |
| OPERATING SYSTEM          |       |                              |                            |        |
| Swing                     | FAIR  | Attn                         | ガタあり SWING: LOOSE          |        |
| Travel                    | FAIR  | Attn                         |                            |        |
| INTERIOR See Photos. 写真参照 |       |                              |                            |        |
| INTERIOR COND.            | CLEAN | FAIR                         | DIRTY                      |        |
| Operator's Seat           | FAIR  | Attn                         |                            |        |
| Glasses                   | FAIR  | Attn                         |                            |        |
| AirCon                    | A/C   | H/C · H only · C only · None |                            |        |
| BOOM / ARM / BKT          |       |                              |                            |        |
| Boom                      | FAIR  | Attn                         |                            |        |
| Boom Cylinder             | FAIR  | Attn                         |                            |        |
| Arm                       | FAIR  | Attn                         | ガタあり LOOSE                 |        |
| Arm Cylinder              | FAIR  | Attn                         |                            |        |
| ATTACHMENT                | FAIR  | Attn                         |                            |        |
| BKT Cylinder              | FAIR  | Attn                         |                            |        |

|                                                                      |                                             |                              |  |  |   |
|----------------------------------------------------------------------|---------------------------------------------|------------------------------|--|--|---|
| UNDERCARRIAGE : See Photos. 写真参照                                     |                                             |                              |  |  |   |
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)         |                                             |                              |  |  | 3 |
| COMMENT<br>左右トラックローラーガタあり SOME TRACK ROLLERS: LOOSE                  |                                             |                              |  |  |   |
| BKT                                                                  | (STD / SLOPE / NARROW / SKELETON / OTHER( ) |                              |  |  |   |
| Lever                                                                | LONG ▪ (WRIST)                              |                              |  |  |   |
| Multi                                                                | (MULTI) ▪ 2 ▪ NO                            |                              |  |  |   |
| ARM-CRANE                                                            | (YES) ▪ NO                                  | 数値ズレあり NUMERICAL DISCREPANCY |  |  |   |
| BLADE                                                                | (YES) ▪ NO                                  |                              |  |  |   |
| OFFSET                                                               | YES ▪ (NO)                                  |                              |  |  |   |
| OFFSET Cylinder                                                      | FAIR ▪ Attn                                 |                              |  |  |   |
| Piping                                                               | (YES) ▪ NO                                  | Breaker only ▪ (Multi)       |  |  |   |
| COMMENT<br>HR メーター不明 HR UNKNOWN                                      |                                             |                              |  |  |   |
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) |                                             |                              |  |  |   |
|                                                                      |                                             |                              |  |  | 3 |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。