

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/8/19	MAKE	CAT	MODEL	303E
SERIAL	CAT0303ECSMG00820		STAMP	CAT0303ECSMG00820	
HR METER	3973	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	300G	

ENGINE : MODEL		C1.3	S/N
Oil leakage	FAIR	Attn	
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	*1
US EPA	YES	NO	
MAIN PUMP			
Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	
COOLING SYSTEM			
Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	
OPERATING SYSTEM			
Swing	FAIR	Attn	
Travel	FAIR	Attn	*2
INTERIOR		See Photos. 写真参照	
INTERIOR COND.	CLEAN	FAIR	DIRTY
Operator's Seat	FAIR	Attn	破れあり CUT
Glasses	FAIR	Attn	
AirCon	A/C	H/C	H only · C only · None
BOOM / ARM / BKT			
Boom	FAIR	Attn	
Boom Cylinder	FAIR	Attn	にじみあり OIL OOZING
Arm	FAIR	Attn	ピンガタあり PIN: LOOSE
Arm Cylinder	FAIR	Attn	
ATTACHMENT	FAIR	Attn	ピンガタあり PIN: LOOSE
BKT Cylinder	FAIR	Attn	

UNDERCARRIAGE :		See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			2
COMMENT			
BKT	STD / SLOPE / NARROW SKELETON OTHER ()		
Lever	LONG	WRIST	
Multi	MULTI	2	NO
ARM-CRANE	YES	NO	
BLADE	YES	NO	
OFFSET	YES	NO	
OFFSET Cylinder	FAIR	Attn	
Piping	YES	NO	Breaker only Multi
COMMENT			
E/Gに負荷を掛けるとE/G振動大			
ENGINE: MUCH VIBRATING WITH ENGINE LOAD INCREASING			
*1 スローの時のみ黒煙あり BLACK FUMES ON LOW ENGINE SPEED WORK			
*2 E/Gスローの時に走行の動き悪い			
*2 SLOW MOVING & DULL MOVING ON LOW ENGINE SPEED WORK			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。