

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/8/21	MAKE	HITACHI	MODEL	ZX120
SERIAL	HCM1S100T00073214			STAMP	HCM1S100T00073214
HR METER	19244	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	500G PADS

ENGINE : MODEL 4BG1 S/N 937972 Oil leakage FAIR · Attn Blow-By FAIR · Attn A LITTLE · MIDDLE · SEVERE Sound FAIR · Attn Oil FAIR · Attn Exhaust Color FAIR · Attn US EPA YES · NO MAIN PUMP Sound FAIR · Attn Oil leakage FAIR · Attn 油汚れあり OIL STAINS Power FAIR · Attn COOLING SYSTEM Radiator FAIR · Attn Oil Cooler FAIR · Attn OPERATING SYSTEM Swing FAIR · Attn ガタあり SWING: LOOSE Travel FAIR · Attn 左足遅い LEFT TRACK: SLOW MOVING INTERIOR See Photos. 写真参照 INTERIOR COND. CLEAN · FAIR · DIRTY Operator's Seat FAIR · Attn 損傷あり DAMAGED Glasses FAIR · Attn *1 AirCon A/C · H/C · H only · C only · None BOOM / ARM / BKT Boom FAIR · Attn Boom Cylinder FAIR · Attn 両側油漏れあり CYLINDERS: OIL LEAKING Arm FAIR · Attn Arm Cylinder FAIR · Attn ATTACHMENT FAIR · Attn ガタあり LOOSE BKT Cylinder FAIR · Attn	UNDERCARRIAGE : See Photos. 写真参照 RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4 COMMENT シューパッド:カスが付いているだけ RUBBER PADS: ALMOST GONE BKT STD / SLOPE / NARROW / SKELETON OTHER FORK GRAB) Lever LONG · WRIST Multi MULTI · 2 · NO ARM-CRANE YES · NO BLADE YES · NO OFFSET YES · NO OFFSET Cylinder FAIR · Attn Piping YES · NO Breaker only · Multi COMMENT FORK GRAB MAKE: TAGUCHI GT120-GT1201200 メインポンプ下底板変形あり UNDER COVER OF BOTTOM OF MAIN PUMP: DEFORMED A/C風が冷えない A/C: MALFUNCTION *1 ドア下側アクリル加工あり LOWER DOOR GLASS: ACRYLIC BOARD RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。