

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/8/4	MAKE	HITACHI	MODEL	EX75US-5
SERIAL	1CAP021004		STAMP	1CAP021004	
HR METER	4273	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	450G PADS	

ENGINE :		MODEL	4JG1	S/N
Oil leakage	FAIR	Attn	*1	
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR	Attn		
Oil	FAIR	Attn		
Exhaust Color	FAIR	Attn		
US EPA	YES	NO		
MAIN PUMP				
Sound	FAIR	Attn		
Oil leakage	FAIR	Attn		
Power	FAIR	Attn		
COOLING SYSTEM				
Radiator	FAIR	Attn		
Oil Cooler	FAIR	Attn		
OPERATING SYSTEM				
Swing	FAIR	Attn	*2	
Travel	FAIR	Attn	*3	
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN	FAIR	DIRTY	
Operator's Seat	FAIR	Attn		
Glasses	FAIR	Attn		
AirCon	A/C	H/C	H only	C only
				None
BOOM / ARM / BKT				
Boom	FAIR	Attn		
Boom Cylinder	FAIR	Attn	サビ大 MUCH RUSTY	
Arm	FAIR	Attn		
Arm Cylinder	FAIR	Attn		
ATTACHMENT	FAIR	Attn	*4	
BKT Cylinder	FAIR	Attn		

UNDERCARRIAGE :						See Photos.						写真参照						
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)										4								
COMMENT																		
BKT	STD / SLOPE / NARROW / SKELETON (OTHER))																	
Lever	LONG ▪ (WRIST)																	
Multi	MULTI ▪ 2 ▪ (NO)																	
ARM-CRANE	YES ▪ (NO)																	
BLADE	(YES) ▪ NO																	
OFFSET	YES ▪ (NO)																	
OFFSET Cylinder	FAIR ▪ Attn																	
Piping	(YES) ▪ NO									Breaker only ▪ Multi								
COMMENT																		
アタッチメント:ピラニアバケット ATTACHMENT: PIRANHA BUCKET																		
ワンタッチ付 W/ONE-TOUCH																		
*1 噴射ポンプ周り油污れあり AROUND INJECTION PUMP: OIL STAINS																		
*2 ガタあり、ブレーキ若干甘い SWING: LOOSE, BRAKE: A LITTLE LOOSE																		
*3 増速ペダル不良 HI/LO SHIFTING PEDAL: MALFUNCTION																		
*4 ガタ、アゴ油圧抜けあり LOOSE, BUCKET JAW: HYDRAULIC DRIFT																		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)										4								

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。