

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/7/28	MAKE	KATO	MODEL	HD308US
SERIAL	8675413	STAMP	UNREADABLE		
HR METER	6154	HR	YEAR		YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	SHOE	450G PADS		

ENGINE : MODEL 4JG1 **S/N** 265520

Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	

MAIN PUMP

Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	配管にじみあり SOME PIPE: OIL OOZING
Power	FAIR · Attn	

COOLING SYSTEM

Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	

OPERATING SYSTEM

Swing	FAIR · Attn	ガタあり SWING: LOOSE
Travel	FAIR · Attn	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN · FAIR · DIRTY
Operator's Seat	FAIR · Attn 破れ小 TINY CUT
Glasses	FAIR · Attn
AirCon	A/C · H/C · H only · C only · None

BOOM / ARM / BKT

Boom	FAIR · Attn	ガタあり LOOSE
Boom Cylinder	FAIR · Attn	油漏れあり OIL LEAKING
Arm	FAIR · Attn	
Arm Cylinder	FAIR · Attn	
ATTACHMENT	FAIR · Attn	*1
BKT Cylinder	FAIR · Attn	油漏れあり OIL LEAKING

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 1

COMMENT

シューパッド摩耗大、剥がれ多数あり RUBBER PADS: ALMOST GONE

BKT STD / SLOPE / NARROW / SKELETON (OTHER))

Lever LONG · WRIST

Multi MULTI · 2 · NO

ARM-CRANE YES · NO

BLADE YES · NO

OFFSET YES · NO

OFFSET Cylinder FAIR · Attn

Piping YES · NO Breaker only · Multi

COMMENT

アタッチメント: ピラニアバケット ATTACHMENT: PIRANHA BUCKET

コントロールバルブ油漏れあり CONTROL VALVE: OIL LEAKING

作動油タンク上にじみ、作動油タンク下油漏れあり

UPPER PART OF HYDRAULIC OIL TANK: OIL OOZING,

BOTTOM OF HYDRAULIC OIL TANK: OIL LEAKING

A/Cコンデンサー破損、HLE表示あり、風が出ない

A/C CONDENSOR: BROKEN, "HLE" ERROR DISPLAY,

A/C: NOT BLOWING AIR

底板油漏れ小 BOTTOM: OIL LEAKING

*1 ガタ、ピラニアバケット油漏れあり LOOSE, OIL LEAKING

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 1

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。