

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/7/28	MAKE	HITACHI	MODEL	EX60-2
SERIAL	10K-34624			STAMP	10K-34624
HR METER	11904	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	450R

ENGINE : MODEL		S/N
Oil leakage	FAIR • ☒ Attn	油汚れ大 MUCH OIL STAINS
Blow-By	☒ FAIR • Attn	A LITTLE • MIDDLE • SEVERE
Sound	☒ FAIR • Attn	
Oil	☒ FAIR • Attn	
Exhaust Color	☒ FAIR • Attn	
US EPA	YES • ☒ NO	
MAIN PUMP		
Sound	☒ FAIR • Attn	
Oil leakage	☒ FAIR • Attn	
Power	☒ FAIR • Attn	
COOLING SYSTEM		
Radiator	☒ FAIR • Attn	
Oil Cooler	☒ FAIR • Attn	
OPERATING SYSTEM		
Swing	FAIR • ☒ Attn	ガタあり SWING: LOOSE
Travel	☒ FAIR • Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN • ☒ FAIR •	DIRTY
Operator's Seat	☒ FAIR • Attn	
Glasses	☒ FAIR • Attn	
AirCon	A/C • H/C • ☒ H only • C only • None	
BOOM / ARM / BKT		
Boom	FAIR • ☒ Attn	ねじれあり DISTORTED
Boom Cylinder	☒ FAIR • Attn	
Arm	☒ FAIR • Attn	
Arm Cylinder	☒ FAIR • Attn	
ATTACHMENT	☒ FAIR • Attn	ガタあり LOOSE
BKT Cylinder	☒ FAIR • Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
BKT	☒ STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG • ☒ WRIST
Multi	MULTI • 2 • ☒ NO
ARM-CRANE	YES • ☒ NO
BLADE	☒ YES • NO
OFFSET	YES • ☒ NO
OFFSET Cylinder	FAIR • Attn
Piping	YES • ☒ NO Breaker only • Multi
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。