

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/8/5	MAKE	CAT	MODEL	E200B
SERIAL	4SG06543			STAMP	4SG06543
HR METER	5093	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	600G

ENGINE : MODEL S6KT **S/N** 008112

Oil leakage	FAIR	Attn	*1
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
US EPA	YES	NO	

MAIN PUMP

Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	油漏れあり OIL LEAKING
Power	FAIR	Attn	

COOLING SYSTEM

Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	

OPERATING SYSTEM

Swing	FAIR	Attn	ガタあり SWING: LOOSE
Travel	FAIR	Attn	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN	FAIR	DIRTY
Operator's Seat	FAIR	Attn	破れあり TORN
Glasses	FAIR	Attn	F下部鉄板 LOWER WINDSHIELD: IRON PLATE
AirCon	A/C	H/C	H only · C only · None

BOOM / ARM / BKT

Boom	FAIR	Attn	補修跡、パッチあり REPAIRED, PATCHED
Boom Cylinder	FAIR	Attn	左右にじみあり CYLINDERS: OIL OOZING
Arm	FAIR	Attn	
Arm Cylinder	FAIR	Attn	
ATTACHMENT	FAIR	Attn	ガタあり LOOSE
BKT Cylinder	FAIR	Attn	傷あり SCRATCHED

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) **3**

COMMENT

.....

.....

.....

.....

BKT (STD / SLOPE / NARROW / SKELETON / OTHER ())

Lever LONG · WRIST

Multi MULTI · 2 · NO

ARM-CRANE YES · NO

BLADE YES · NO

OFFSET YES · NO

OFFSET Cylinder FAIR · Attn

Piping YES · NO Breaker only · Multi

COMMENT

コントロールバルブ油漏れあり CONTROL VALVE: OIL LEAKING

プレート外側欠 PLATE ON REVOLVING FRAME: MISSING

左サイドカバー欠 LEFT SIDE COVER: MISSING

メーター不良 INDICATOR: MALFUNCTION

ポンプ周りホース油漏れ小 SOME HOSES AROUND PUMP: OIL LEAKING

CABドアラッチ掛からない DOOR LATCH: MALFUNCTION

*1 オイルパン周り油漏れ小 AROUND OIL PAN: OIL LEAKING

.....

.....

.....

.....

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) **2**

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。