

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/8/21	MAKE	SUMITOMO	MODEL	SH200CT-2
SERIAL	200C2-1664			STAMP	200C2-1664
HR METER	16137	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	600G

ENGINE : MODEL 6BG1 S/N	
Oil leakage	FAIR · ☒ Attn *1
Blow-By	FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn
Oil	FAIR · Attn
Exhaust Color	FAIR · Attn
US EPA	YES · ☒ NO
MAIN PUMP	
Sound	FAIR · Attn
Oil leakage	FAIR · ☒ Attn 油漏れあり OIL LEAKING
Power	FAIR · Attn
COOLING SYSTEM	
Radiator	FAIR · Attn
Oil Cooler	FAIR · Attn
OPERATING SYSTEM	
Swing	FAIR · Attn
Travel	FAIR · Attn
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · FAIR · ☒ DIRTY
Operator's Seat	FAIR · Attn 破れあり HUGE CUTS
Glasses	FAIR · Attn
AirCon	A/C · H/C · H only · C only · None
BOOM / ARM / BKT	
Boom	FAIR · Attn
Boom Cylinder	FAIR · ☒ Attn 左右油漏れあり CYLINDERS: OIL LEAKING
Arm	FAIR · Attn ガタあり LOOSE
Arm Cylinder	FAIR · Attn
ATTACHMENT	FAIR · Attn ガタあり LOOSE
BKT Cylinder	FAIR · ☒ Attn 油漏れ小 OIL LEAKING

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
COMMENT	
左右シュールリンク、プレートガタ多数あり	
MANY TRACK LINKS & SHOE PLATES: LOOSE	
右トラックローラーガタあり SOME RIGHT TRACK ROLLERS: LOOSE	
底板油汚れあり BOTTOM: OIL STAINS	
BKT	☒ STD / ☐ SLOPE / ☐ NARROW / ☐ SKELETON / OTHER ()
Lever	LONG · ☒ WRIST
Multi	☒ MULTI · 2 · NO *2
ARM-CRANE	YES · ☒ NO
BLADE	YES · ☒ NO
OFFSET	YES · ☒ NO
OFFSET Cylinder	FAIR · Attn
Piping	☒ YES · NO ☒ Breaker only · Multi *3
COMMENT	
ブーム背面ホースひび割れあり SOME HOSE AROUND BOOM: CRACKED	
左右サイドカバー欠 SIDE COVERS: MISSING	
*1 オイルフィルター周りにじみあり	
*1 AROUND ENGINE OIL FILTER: OIL OOZING	
*2 レバー周りにじみあり AROUND LEVER: OIL OOZING	
*3 手前側踏めるが油圧起きない	
*3 STEPPING ON THE PEDAL ON THE OPERATOR SIDE:	
UNABLE TO SUPPLY ANY HYDRAULIC PRESSURE	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。