

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/8/3	MAKE	KATO	MODEL	HD820-6
SERIAL	KWJ21E01TG0005943		STAMP	5943	
HR METER	7876	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

ENGINE : MODEL		4M50	S/N	D97098
Oil leakage	FAIR	Attn		
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR	Attn		
Oil	FAIR	Attn		
Exhaust Color	FAIR	Attn		
US EPA	YES	NO		
MAIN PUMP				
Sound	FAIR	Attn		
Oil leakage	FAIR	Attn		
Power	FAIR	Attn		
COOLING SYSTEM				
Radiator	FAIR	Attn	サブタンク破損あり SUB TANK: DAMAGED	
Oil Cooler	FAIR	Attn		
OPERATING SYSTEM				
Swing	FAIR	Attn		
Travel	FAIR	Attn		
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN	FAIR	DIRTY	
Operator's Seat	FAIR	Attn		
Glasses	FAIR	Attn	F下部欠 LOWER WINDSHIELD: MISSING	
AirCon	A/C	H/C	H only	C only
None				
BOOM / ARM / BKT				
Boom	FAIR	Attn		
Boom Cylinder	FAIR	Attn		
Arm	FAIR	Attn	ガタあり LOOSE	
Arm Cylinder	FAIR	Attn		
ATTACHMENT	FAIR	Attn		
BKT Cylinder	FAIR	Attn		

UNDERCARRIAGE :						See Photos.	写真参照
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)							4
COMMENT							
BKT	STD	SLOPE	NARROW / SKELETON / OTHER()				
Lever	LONG	WRIST					
Multi	MULTI	2 NO					
ARM-CRANE	YES	NO					
BLADE	YES	NO					
OFFSET	YES	NO					
OFFSET Cylinder	FAIR	Attn					
Piping	YES	NO	Breaker only	Multi			
COMMENT							
ボディリペイントあり BODY: REPAINTED							
底板へコミ多数あり BOTTOM: MUCH DENT							
電気系統エラー表示あり "E61" ERROR DISPLAY FOR ELECTRIC SYSTEM							
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)							1

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。