

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/8/20	MAKE	KOMATSU	MODEL	PC200I-11
SERIAL	505426		STAMP	KMTPC257HMC505426	
HR METER	6085	HR	YEAR	2021	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

ENGINE : MODEL		6D107E-3		S/N		26736004	
Oil leakage	FAIR	Attn					
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE				
Sound	FAIR	Attn					
Oil	FAIR	Attn					
Exhaust Color	FAIR	Attn					
US EPA	YES	NO					
MAIN PUMP							
Sound	FAIR	Attn					
Oil leakage	FAIR	Attn					
Power	FAIR	Attn					
COOLING SYSTEM							
Radiator	FAIR	Attn					
Oil Cooler	FAIR	Attn					
OPERATING SYSTEM							
Swing	FAIR	Attn					
Travel	FAIR	Attn					
INTERIOR See Photos. 写真参照							
INTERIOR COND.	CLEAN	FAIR	DIRTY				
Operator's Seat	FAIR	Attn					
Glasses	FAIR	Attn					
AirCon	A/C	H/C	H only	C only	None		
BOOM / ARM / BKT							
Boom	FAIR	Attn					
Boom Cylinder	FAIR	Attn					
Arm	FAIR	Attn					
Arm Cylinder	FAIR	Attn					
ATTACHMENT	FAIR	Attn					
BKT Cylinder	FAIR	Attn	傷あり SCRATCHED				

UNDERCARRIAGE :		See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3	
COMMENT			
BKT	STD	SLOPE / NARROW / SKELETON / OTHER ()	
Lever	LONG	WRIST	
Multi	MULTI	2	NO
ARM-CRANE	YES	NO	
BLADE	YES	NO	
OFFSET	YES	NO	
OFFSET Cylinder	FAIR	Attn	
Piping	YES	NO	Breaker only Multi
COMMENT			
！マーク、シリンダーマーク、L01システム異常表示あり			
WARNING LAMPS: ON, "L01" ERRORS DISPLAY FOR SYSTEM			
ICT機器用SIMカードを取り外したためのエラー、作業に問題はなし			
"L01" ERRORS FOR ICT, NO PROBLEM FOR THE NORMAL OPERATION			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。