

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/7/30	MAKE	KOMATSU	MODEL	PC228US-3N0
SERIAL	31102		STAMP	KMTPC057P02031102	
HR METER	7734	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	800G	

ENGINE : MODEL		6D102E-2		S/N		26344458	
Oil leakage	FAIR	Attn					
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE				
Sound	FAIR	Attn					
Oil	FAIR	Attn					
Exhaust Color	FAIR	Attn					
US EPA	YES	NO					
MAIN PUMP							
Sound	FAIR	Attn					
Oil leakage	FAIR	Attn					
Power	FAIR	Attn					
COOLING SYSTEM							
Radiator	FAIR	Attn					
Oil Cooler	FAIR	Attn					
OPERATING SYSTEM							
Swing	FAIR	Attn					
Travel	FAIR	Attn	増速S/W不良 HI/LO SWITCH: MALFUNCTION				
INTERIOR See Photos. 写真参照							
INTERIOR COND.	CLEAN	FAIR	DIRTY				
Operator's Seat	FAIR	Attn					
Glasses	FAIR	Attn					
AirCon	A/C	H/C	H only	C only	None		
BOOM / ARM / BKT							
Boom	FAIR	Attn					
Boom Cylinder	FAIR	Attn					
Arm	FAIR	Attn					
Arm Cylinder	FAIR	Attn	油漏れあり OIL LEAKING				
ATTACHMENT	FAIR	Attn	ガタあり LOOSE				
BKT Cylinder	FAIR	Attn	にじみあり OIL OOZING				

UNDERCARRIAGE :		See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		2	
COMMENT			
両側シューリンク固着あり TRACK LINKS: STUCK			
BKT	STD	SLOPE / NARROW / SKELETON / OTHER (	)
Lever	LONG	WRIST	
Multi	MULTI	2	NO
ARM-CRANE	YES	NO	
BLADE	YES	NO	
OFFSET	YES	NO	
OFFSET Cylinder	FAIR	Attn	
Piping	YES	NO	Breaker only Multi
COMMENT			
配管油圧ホース劣化あり SOME HOSES: DETERIORATED			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。