

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/7/27	MAKE	KOMATSU	MODEL	PC55MR-5
SERIAL	23581		STAMP	KMTPC259ENE023581	
HR METER	2144	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	400G PADS	

ENGINE : MODEL		S/N
Oil leakage	☒ FAIR · Attn	
Blow-By	☒ FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	☒ FAIR · Attn	
Oil	☒ FAIR · Attn	
Exhaust Color	☒ FAIR · Attn	
US EPA	☒ YES · NO	
MAIN PUMP		
Sound	☒ FAIR · Attn	
Oil leakage	☒ FAIR · Attn	
Power	☒ FAIR · Attn	
COOLING SYSTEM		
Radiator	☒ FAIR · Attn	
Oil Cooler	☒ FAIR · Attn	
OPERATING SYSTEM		
Swing	☒ FAIR · Attn	
Travel	☒ FAIR · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · ☒ FAIR · DIRTY	
Operator's Seat	☒ FAIR · Attn	
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · ☒ None	
BOOM / ARM / BKT		
Boom	☒ FAIR · Attn	
Boom Cylinder	☒ FAIR · Attn	
Arm	☒ FAIR · Attn	
Arm Cylinder	☒ FAIR · Attn	
ATTACHMENT	☒ FAIR · Attn	
BKT Cylinder	FAIR · ☒ Attn	傷あり SCRATCHED

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
BKT	STD / SLOPE / NARROW ☒ SKELETON OTHER()
Lever	LONG · ☒ WRIST
Multi	MULTI · 2 · ☒ NO
ARM-CRANE	YES · ☒ NO
BLADE	☒ YES · NO
OFFSET	YES · ☒ NO
OFFSET Cylinder	FAIR · Attn
Piping	☒ YES · NO Breaker only · ☒ Multi
COMMENT	
リペイントあり REPAINTED	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。