

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/8/25	MAKE	KATO	MODEL	KR-25H-V7
SERIAL No.	PLATE : 5110338		STAMP : KRC005-0338		
HR METER	15145	HR	Odometer	64259	km
TIRE SIZE	385/95R25		YEAR	YR	

ENGINE : MODEL		S/N
Oil leakage	FAIR (Attn)	下部油漏れあり BOTTOM OF ENGINE: OIL LEAKING
Blow-By	FAIR (Attn)	A LITTLE ・ MIDDLE ・ SEVERE
Sound	FAIR (Attn)	
Oil	FAIR (Attn)	
Exhaust Color	FAIR (Attn)	

OPERATION PUMP

Sound	FAIR	Attn
Oil leakage	FAIR	Attn
Power	FAIR	Attn

COOLING SYSTEM

Radiator	FAIR • Attn
Oil Cooler	FAIR • Attn

OPERATING SYSTEM

Computer	OK	NG
Swing	FAIR	Attn
Travel	FAIR	Attn

TRANSMISSION

Transmission	FAIR • Attn
No. OF GEARS	4
4WD	4WD • 6WD

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN	•	FAIR	•	DIRTY
----------------	-------	---	------	---	-------

Operator's Seat	FAIR	Attn	*1
-----------------	------	------	----

Glasses	FAIR • Attn
---------	-------------

AirCon (A/C) · H/C · H only · C only · None

COMMENT

BOOM

No. of Section	4 SECTIONS
----------------	------------

CRACK/ENFORCEMENT	FAIR	▪ Attr
-------------------	------	--------

DERRICKING CYL.	FAIR	▪ Attr
-----------------	------	--------

EXTENSION CYL. (FAIR) ▪ Attr

JIB	☒ YES ▪ NO
-----	---

JIB TYPE	STD ▪ (PWR
----------	------------

MAIN & SUB WIRE	☒ YES	☐ NO
-----------------	--------------------------------------	--------------------------

FREE FALL	YES • (NO)
-----------	-------------------

HOOK	25t, BALL
------	-----------

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
---	----------

TIRE WEAR	FAIR • WORN • UNEVEN WEAR
-----------	---------------------------

COMMENT

OUTRIGGERS

OUTRIGGERS	X · (H
------------	--------

OUTRIGGERS COND.	FAIR	▪ Attr
------------------	------	--------

Oil leakage (JACK CYL.)	FRONT	L · R	REAR	L · R
-------------------------	-------	-------	------	-------

Oil leakage (SLIDE CYL.)	FRONT	L · R	REAR	L · R
--------------------------	-------	-------	------	-------

COMMENT

*1 シートクッション不良 SEAT CUSHION: MALFUNCTION

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。