

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/8/7	MAKE	KOBELCO	MODEL	SK200
SERIAL	NO PLATE			STAMP	YN-16474
HR METER	2530	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	600G

ENGINE : MODEL 6D31 S/N	
Oil leakage	FAIR • ☒ Attn *1
Blow-By	FAIR • Attn A LITTLE • MIDDLE • SEVERE
Sound	FAIR • Attn
Oil	FAIR • Attn
Exhaust Color	FAIR • ☒ Attn 黒煙あり BLACK FUMES
US EPA	YES • ☒ NO
MAIN PUMP	
Sound	FAIR • Attn
Oil leakage	FAIR • Attn
Power	FAIR • Attn
COOLING SYSTEM	
Radiator	FAIR • Attn
Oil Cooler	FAIR • Attn
OPERATING SYSTEM	
Swing	FAIR • ☒ Attn 遅い SLOW MOVING
Travel	FAIR • ☒ Attn *2
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN • FAIR • ☒ DIRTY
Operator's Seat	FAIR • ☒ Attn 破れあり TORN
Glasses	FAIR • Attn
AirCon	A/C • ☒ H/C • H only • C only • None
BOOM / ARM / BKT	
Boom	FAIR • Attn 右側溶接あり RIGHT SIDE: WELDED
Boom Cylinder	FAIR • ☒ Attn *3
Arm	FAIR • Attn
Arm Cylinder	FAIR • ☒ Attn *4
ATTACHMENT	FAIR • Attn シリンダーにじみあり CYLINDER: OIL OOZING
BKT Cylinder	FAIR • ☒ Attn にじみあり OIL OOZING

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
COMMENT	
下部走行帯フレーム溶接あり MAIN FRAME: WELDED	
左リンクピッチ伸びあり LEFT TRACK LINKS: WORN	
スイベルジョイント油漏れあり(吸着マットあり)	
SWIVEL JOINT: OIL LEAKING (W/ABSORPTION MAT)	
BKT	STD / SLOPE / NARROW / SKELETON ☒ OTHER CUTTER
Lever	LONG • ☒ WRIST
Multi	☒ MULTI • 2 • NO
ARM-CRANE	YES • ☒ NO
BLADE	YES • ☒ NO
OFFSET	YES • ☒ NO
OFFSET Cylinder	FAIR • Attn
Piping	☒ YES • NO Breaker only ☒ Multi
COMMENT	
クランプアームシリンダーにじみあり(吸着マットあり)	
CLAMP ARM CYLINDER: OIL OOZING (W/ABSORPTION MAT)	
コントロールバルブ付近油漏れあり AROUND CONTROL VALVE: OIL LEAKING	
ブーム下付近ホース油漏れあり(吸着マットあり)	
SOME PIPE AROUND LOWER PART OF BOOM: OIL LEAKING (W/ABSORPTION MAT)	
*1 ヘッドカバー、E/G周りにじみあり AROUND HEAD COVER & ENGINE: OIL OOZING	
*2 左弱いため前後進時左に寄る	
*2 TOTTERING TO LEFT (LEFT TRACK: WEAK POWER)	
*3 右油漏れあり(吸着マットあり)	
*3 RIGHT CYLINDER: OIL LEAKING (W/ABSORPTION MAT)	
*4 油漏れあり(吸着マットあり) CYLINDER: OIL LEAKING (W/ABSORPTION MAT)	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。